

AD-A040 130

PARKS COLL OF SAINT LOUIS UNIV CAHOKIA ILL
APPLICATIONS OF THE SHOCK PULSE TECHNIQUE TO HELICOPTER DIAGNOS--ETC(U)
FEB 75 T C MAYER, E F COVILL, J A GEORGE

F/G 1/3


DAAJ01-72-A-0027


USAAVSCOM-TR-77-21

NL

UNCLASSIFIED

1 OF 3
AD
A040 130





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

2-10
USAAVSCOM TR 77-21


AD A 040 130

APPLICATIONS OF THE SHOCK PULSE TECHNIQUES TO HELICOPTER DIAGNOSTICS

Timothy C. Mayer
Edward F. Covill
John A. George
J. Thomas Harrington

24 February 1975

Final Report.



APPROVED FOR PUBLIC RELEASE:
DISTRIBUTION UNLIMITED

Prepared for
Directorate for Research, Development, and Engineering
U.S. ARMY AVIATION SYSTEMS COMMAND
P.O. Box 209
St. Louis, MO 63166



AD No. _____
DDC FILE COPY

DISCLAIMERS

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission, to manufacture, use, or sell any patented invention that may in any way be related thereto.

Trade names cited in this report do not constitute an official endorsement or approval of the use of such commercial hardware or software.

DISPOSITION INSTRUCTIONS

Destroy this report when no longer needed. Do not return it to the originator.

FINAL REPORT

APPLICATIONS OF THE SHOCK PULSE TECHNIQUE TO HELICOPTER DIAGNOSTICS

PART I

TIMOTHY C. MAYER
EDWARD F. COVILL
JOHN A. GEORGE
J. THOMAS HARRINGTON

1	White Section	<input checked="" type="checkbox"/>
2	Blue Section	<input type="checkbox"/>
3	Red Section	<input type="checkbox"/>
DISTRIBUTION/AVAILABILITY CODES		
Dist.	Avail.	Special
A		

PARKS COLLEGE OF SAINT LOUIS UNIVERSITY
CAHOKIA, ILLINOIS
FEBRUARY 24, 1975

BOA DAAJ01-72-A-0027 (P6C)
DO DAAJ01-72-A-0027-0001 (P6C)
DO DAAJ01-72-A-0027-0002 (P6C)

ABSTRACT

APPLICATIONS OF THE SHOCK PULSE TECHNIQUE TO HELICOPTER DIAGNOSTICS

An investigation has been carried out on the feasibility of shock pulse techniques in the detection of failures in helicopter power trains. A standard off-the-shelf SKF Industries model MEPA-10A was employed to construct shock emission envelopes of shock rate versus shock level. Data was collected from the hanger bearings of the tail rotor, drive shaft assembly, the 42° and 90° gear box assemblies, and the transmission and mast assemblies as installed on operational UH-1 series helicopters. Further data was obtained on the OH-58 as well as from helicopters at Fort Rucker, Alabama with implanted bearings of known condition. The correlation between the shock emission envelopes and degree of degradation as revealed by teardown analysis is described. Laboratory tests were conducted to determine the condition of gears in the 42° gear box through the use of shock emissions. The shock pulse meter shows promise for its ability to separate those components with normal wear, or the onset of damage, from those with severe damage.

FOREWARD

This report presents the results of the analysis of the SKF Industries, Inc. MEPA-10A Shock Pulse Meter conducted by Parks College of Saint Louis University with SKF Industries of King of Prussia, Pennsylvania, as a subcontractor.


Parks College gratefully acknowledges the support and assistance of the United States Army Aviation Systems Command (USAAVSCOM) Flight Operations Division, St. Louis, MO; Hawthorn Aviation, Fort Rucker, AL; Bell Helicopter Co., Ft. Worth, TX; United States Army Flight Test Board, Fort Rucker, AL; and the 102d USARFFAC, Cahokia, IL.




Mr. Timothy C. Mayer
Research Associate



Mr. Edward F. Covill
Research Associate



Dr. John A. George
Technical Director



J. Thomas Harrington
Director of Research

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

A REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 18 USAVSCOM TR-77-21	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Applications of the Shock Pulse Technique to Helicopter Diagnostics.	5. TYPE OF REPORT & PERIOD COVERED Final Report.	
7. AUTHOR(s) Timothy C. Mayer Edward F. Covill John A. George J. Thomas Harrington		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Parks College St. Louis University Cahokia, Illinois 62206		8. CONTRACT OR GRANT NUMBER(s) DAAJ01-A-0027 (P6C) DAAJ01-72-A-0027-0001 (P6C) DAAJ01-72-A-0027-0002 (P6C)
11. CONTROLLING OFFICE NAME AND ADDRESS Directorate for RDandE. U.S. Army Aviation Systems Command P.O. Box 209 St. Louis, MO 63166		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE 24 February 1975
		13. NUMBER OF PAGES 270
		15. SECURITY CLASS. (of this report) unclassified
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Shock Diagnostic Equipment Pulses AIDAPS Test Bed Program Helicopter Rotors Condition Monitoring Helicopters Drives		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) An investigation has been carried out on the feasibility of shock pulse techniques in the detection of failures in helicopter power trains. A standard off-the-shelf SKF Industries model MEPA-10A was employed to construct shock emission envelopes of shock rate versus shock level. Data was collected from the hanger bearings of the tail rotor drive shaft assembly, the 42° and 90° gear box assemblies, and the transmission and mast assemblies as installed on operational UH-1 series helicopters. Further data was obtained on the OH-58 as		

DDC
JUN 1 1975
RECEIVED

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

449244 only

unclassified

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

well as from helicopters at Fort Rucker, Alabama with implanted bearings of known condition. The correlation between the shock emission envelopes and degree of degradation as revealed by teardown analysis is described. Laboratory tests were conducted to determine the condition of the gears in the 42⁰ gear box through the use of shock emissions. The shock pulse meter shows promise for its ability to separate those components with normal wear, or the onset of damage, from those with severe damage.

unclassified

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

TABLE OF CONTENTS

Part I

- 1.0 INTRODUCTION
- 2.0 EXPLANATION OF THE MEPA-10A SYSTEM
- 3.0 LABORATORY FINDINGS
- 4.0 FIELD STUDY
 - 4.1 HANGER BEARINGS
 - 4.2 42° GEAR BOX
 - 4.3 90° GEAR BOX
 - 4.4 MAST BEARING
 - 4.5 TRANSMISSION INPUT DRIVE QUILL
- 5.0 FLIGHT TEST DATA
- 6.0 RESULTS AND CONCLUSIONS

Part II

- 7.0 TABLES AND APPENDICES

1.0 INTRODUCTION

The United States Army Aviation Systems Command (USAAVSCOM) has an ongoing program to develop a system which will automatically accomplish inspection, diagnostic, and prognostic maintenance functions on related subsystems of the UH-1 helicopter. This program, called AIDAPS, is intended to provide equipment which will contribute to an increase in the tactical mobility of Army aviation operations and provide an effective reduction in aircraft maintenance costs and maintenance related accidents.

Past efforts ¹⁻⁴ have included the collection of vibration data with a subsequent analysis of the resulting Power Spectral Densities to determine the condition of the helicopter power train. Another approach, particularly in determining bearing condition, is to use shock pulse techniques. The technique and instrumentation were developed by AB SKF, Sweden and are available in the United States through SKF Industries, Inc., King of Prussia, Pennsylvania. Parks College was placed under contract to AVSCOM to conduct an intensive evaluation of the shock pulse diagnostic technique to helicopters. This report summarizes the effort to date ⁵⁻⁸.

Part I of the report briefly reviews the operation of the shock pulse meter and the generation of the shock emission curve. The shock emission curve is the basic starting point for analysis. Findings of the preliminary laboratory analysis on bearings as well as a laboratory study in detecting gear damage on the UH-1 42⁰ gear box are presented. A summary is

given of data which was collected from the hanger bearings of the tail rotor drive shaft assembly, the 42° and 90° gear box assemblies, and the transmission and mast assemblies as installed on operational UH-1 series helicopters. Further data was obtained from the AIDAPS helicopters at Fort Rucker, Alabama with implanted bearings of known condition. The correlation between the shock emission envelopes and degree of degradation as revealed by teardown analysis is described.

Part II of the report is a compilation of all data collected during this effort. In addition, the complete study in detecting gear damage, made by SKF under subcontract to the College is included.

2.0 EXPLANATION OF THE MEPA-10A SYSTEM

As an alternative diagnostic method in bearing analysis, the SKF MEPA-10A shock pulse technique was used to determine bearing condition. The technique employed is to construct a shock emission envelope containing the rate of shock emission as well as the measurement of the amplitude of shock developed by a particular bearing. When a bearing race or rolling element contains a discrete fault, such as a pit or spall, the contact between this fault and the rolling elements will result in repetitive impacts of short duration. As a result of these impacts, a shock wave propagates through the structure. The shock pulse travels through the bearing and causes a pulse displacement input to an accelerometer. The equipment used in the MEPA-10A system includes a 38 KHZ resonance response accelerometer. The output of the accelerometer is passed through a high gain amplifier tuned at the resonant frequency of the accelerometer. This amplifier acts as a very sharp band-pass filter. After the signal is suitably processed, the output is displayed on a counter which provides the frequency of peaks above any desired peak amplitudes. No other processing is required for the analysis.

A graph is made of the shock emissions and from this data a determination of condition is made. With the accelerometer attached, an initial rate and value evaluation is made. The rate found becomes the first point plotted on the ordinate at a shock level of one. A threshold varying dial, on the MEPA-10A meter housing, ranges from a level of one to ten thousand on a logarithmic scale. As the threshold is increased, successive rates are plotted until a curve

SHOCK PULSE TECHNIQUE AS A DIAGNOSTIC
TOOL FOR HELICOPTERS




Fig 1

crosses the abscissa. The value at the intercept becomes the highest potentiometer level at which at least one shock pulse per second can be measured. Rate values are in pulses per second and shock level obtained is in relation to the displacement of the accelerometer used. The curves drawn are evaluated by their general curve form and the magnitude of rates and/or levels obtained.

The meter is logarithmically integrated and the movement is approximately 90° . Since a logarithmic scale is employed, the reading from 0° to 80° 's of movement corresponds to 0 to 1000 on the meter, while the remaining 10° 's consists of readings 1000 to 10,000. Because of this situation, and that, the first point plotted is dependent on one reading along the ordinate, needle swing may cause difficulty in initial rate determination. This does not affect the shock level and yields no overall impediment in determining bearing condition.

SKF Industries indicates in their operator's manual, included with the MEPA-10A, that all curves plotted are a variation of three general forms 1) one with high rates and relatively low levels - an apparent indication of foreign matter in the lubricant of the bearing, 2) a curve shape of low rates and levels of shock values which reach a relatively high degree - a curve slope indicative of a bearing with insufficient lubricant or possible element damage. 3) a curve with both significantly high values in rate and level - the amount of "filling out" of this curve would be proportionate to the extent which the damage is encountered in the bearing. (Fig. 2.0)




Fig. 2.0

Of the curves plotted on bearings with either known damage or of unknown condition, no case has been documented which fit the precise theoretical forms as described. Although the amount and type of damage approximates the theoretical shapes, the assessment of damage relies on an overall evaluation of the curve, any slope irregularities, as well as magnitude of rate and values.

Because of size and portability of the equipment used, the MEPA-10A shock pulse method was operated in both laboratory and field environments.

3.0 LABORATORY FINDINGS

Bearing Tests

The first use of the shock pulse technique performed by Parks College was on an AIDAPS test aircraft operated at Granite City Army Depot. Although this was technically not a laboratory use, it was the first attempt to establish the methods used in shock pulse analysis. Data was collected in order to become familiar with the technique of analysis, to identify areas where further study could profitably be undertaken, and to investigate consistency and accuracy of data collection. It was found that there was a difference in the shock emission curves of good and degraded hanger bearings installed on the UH-1H helicopter (Fig. 3.0). Several questionable areas arose during this initial phase which precipitated a laboratory study under more closely controlled conditions than a field environment could provide. This study was undertaken to determine the nature of the different curve shapes which could be plotted and evaluate the threshold of damage. A MEPA-10A analyzer coupled with several other pieces of electronic equipment were used on bearings rotating at, approximately, constant speeds. All bearings analyzed were of the same type, make, and size as those employed as hanger bearings on UH-1 series helicopters. The hanger bearing fixture was identical to that of an operational helicopter. Several accelerometer attaching methods were evaluated in order to achieve consistent and reproducible data. An oscilloscope was used keyed to the rotational frequency in attempt to correlate shock emissions depicted with known damage.




Fig. 3.0

Figure 3.1 shows the differences in the shock emissions of new bearings compared to bearings with an unserviceable condition which were rejected for use in aircraft by the US Army inspection facility USAAVNS, Ft. Rucker, Alabama. The higher rates and levels of the unserviceable bearings are apparent. Figure 3.2 is made from a comparison of three specific types of damage: 1) Dirty lubricant, 2) Rolling element damage, 3) "Dry bearing" with insufficient lubricant. The damage was induced artificially on new bearings which are represented on the graph as data scatter of new bearings. There is little correlation to the theoretical curve shapes of Figure 2.0. However, again the rates and levels of the damaged bearings are greater than those of new or undamaged ones.

Figure 3.3 illustrates the speed dependence of the shock emission envelope using a bearing run at two speeds with other conditions such as accelerometer attachment, temperature, and bearing load, held constant. The bearing used had lubricant which contained foreign particulate matter. Figure 3.4 shows the change that can occur in the damage profile over a time interval. A bearing with damage to the "inner race" was monitored over a 100 minute continuous run. The conditions of the test were held constant over this period.

The use of an oscilloscope as an aid in depicting the shock emissions proved of little relative value because of both the difficulty in keying the amplitude of sweep traces to shock levels and the problem of isolating a single revolution of the inner/outer races of the bearing. Very little additional diagnostic information was gained and therefore not employed in further analysis.




Fig. 3.1




Fig. 3.2




Fig. 3.3




Fig. 3.4

One of the first problems which confronted the gathering of data was in accelerometer attachment. A device similar to a vice grip pliers with an accelerometer attached to one jaw was included in the equipment accessories. It was found that using the vice grip device did not allow for enough consistency to insure reproducible data. A number of attachment methods were employed before a suitable one was found. The present device, a pressure clamp which is attached to the lands of the mounting bolts for a component, was used on all field test aircraft. By designing five separate attaching fixtures, designated as VD 1-5, most components with bearings can be quickly and easily analyzed and yet assure reproducibility of the data. Figure 3.5 shows a comparison of variations of accelerometer attachments that were tested. It is apparent that the type of attachment strongly influences the shock emission curve. Figure 3.6 shows the same hanger bearing tested on both an aircraft and the laboratory environment. This indicates damage thresholds determined by laboratory tests would not be appropriate.

Gear Tests

SKF Industries, under subcontract to the College, was tasked to evaluate the ability of the MEPA-10A to detect gear sourced shocks. The College provided technical assistance and monitored the performance of the task. Three UH-1 helicopter 42 degree gear boxes with several different types of gear damage were subjected to shock pulse monitoring during runs at two different loads and at two speeds.





Figure 3.5

4 HANGER BEARINGS

UH-1H TAIL #66-01087

TEST CONDUCTED 28 NOV 1973



GRAPH OF BEARING #A2037362 WHICH WAS REMOVED FOR ANALYSIS BECAUSE OF EXCESSIVE PLAY DISCOVERED BY AN AIRCRAFT TECHNICAL INSPECTOR - ONE GRAPH MADE ON AIRCRAFT, THE OTHER IN LABORATORY AT APPROXIMATELY THE SAME RPM. (14 DEC 1973).

Fig. 3.6

The following has been determined:

1. The MEPA-10A as used can supply warnings as to the onset of damage in a gear box. If damage originates in the bearings, an indication directly correlated with damage is received. If the damage originates in gears, the indication is due to the sensing of particulate contaminant passing through the bearings.
2. The MEPA-10A appears capable of detecting a secondary effect of gear damage in an operating 42⁰ UH-1 helicopter gear box since, in this gear box, the lubricant is captive in the gear box. Metal chips and particles are the products of the mesh of damaged gear teeth and tend to pass through the bearings as the oil in the gear box circulates. Shock level and rate increases accompany their passage.
3. The shock pulse technique has again proven successful in isolating a damaged bearing in a gear box. Standard shock pulse analysis techniques (shock emission profile) using the MEPA-10A were not found in the present study to provide a direct indication of the degree of gear damage.
4. Vibrational velocity measurement, analyzing the signal either in three, two and one-half octave bands, or one-third octave analysis of the audio-

frequency spectrum has failed to provide any consistent indication of damage.

Figure 3.7 illustrates the ability of the shock pulse technique to isolate foreign matter present in the lubricant of a 42^o gear box run on a laboratory test facility. The foreign matter was a result of debris from damaged gears implanted in the assembly.




Fig. 3.7

4.0 FIELD STUDY

The data presented in this section are selected typical evaluations of various components analyzed from the following helicopters:


- 1) UH-1 series models H, D, M and C
- 2) OH-58

Shock pulse signatures were made using a standard MEPA-10A shock pulse meter and all accelerometer mounts were with a pressure clamp device (VD 1-5). Each individual type component was tested with the accelerometer mounted as closely as possible in the same position relative to the bearing assembly (Fig. 4.0). Except as noted, all aircraft were run at 6600 rpm N₂ with no anti-torque pedal application. The areas of study are as follows:

- 1) Hanger bearing assembly
- 2) 42° gear box
- 3) 90° gear box
- 4) Mast bearing
- 5) Transmission input drive quill

This by no means represents all of the components which could have been analyzed. All testing was completed on a non-interference basis with military aircraft, Active and Reserve, normal operational scheduling. The accelerometer mounts were designed with this non-interference constraint in mind so component removal would not be necessary to install the testing fixture. Certain assemblies of the hanger bearing assemblies, 42° gear box, 90° gear box and mast bearing were removed from the aircraft, disassembled to inspect the bearings, and damage correlated with shock depictions. In addition, whenever possible the replacement component was

analyzed to verify that shock emission returned to a lower state. Section 7.0 (Tables and Appendices) of this report contains the bulk of data collected from assemblies tested. A representative group is reviewed in this summary report. The level of shock pulse emissions coupled with its rate and general curve form plotted on each type component is viewed in relation to the same type component to evaluate the bearing.



42° Gear Box



90° Gear Box



Drive Quill



Mast Bearing



Hanger Bearing

Fig. 4.0

4.1 HANGER BEARINGS

Approximately 72 hanger bearings (Fig. 4.1) were tested on UH-1 and OH-58 type helicopters. The following graph (Fig. 4.2) represents one taken from a typical analysis of a hanger bearing which was found to be damaged. After the graph was plotted, a teardown and damage summary was made to correlate the plotted shock emissions.

A shock rate of 340 and level of 700 was considered excessive at the time of the analysis, however, the level is significantly lower than the mean level of the 1800 for hanger bearings removed for testing. This hanger bearing had damage which could be classified as marginal. The ability to detect the onset of damage is of significant value in predicting component failure. The following is a summary of the damage found at teardown:

FSN: 3110-911-8384

PN: 204-040-600-9

SN: A20-44891

Outer Race: Metal Fatigue, Pitting, Flaking Corrosion


Inner Race: Corrosion, Pitting

Rolling Elements: Corrosion, Pitting

When viewing the pictorial evidence (Fig. 4.3), it is relatively simple to correlate damage with shock emissions on the single bearing fixture. By comparing the graph of new or "O" time replacement, it is possible to see the appearance of damage vs undamaged components.

The extensive hanger bearing data has been summarized in a single damage-assessment shock emission curve (Fig. 4.4). The

data indicates a new or normal wear hanger bearing would have a shock level of less than 500 units.



HANGER BEARING ASSEMBLY
 ARROW DENOTES SENSOR LOCATION




Fig. 4.2




Hanger Bearing
P/N A20-44891
A/C 65-9519

Fig. 4.3

GRAPH FOR BEARING ASSEMBLIES

ANALYZED IN FIELD EVALUATION OF SHOCK PULSE TECHNIQUES



GREEN AREA SIGNIFIES BEARING IN GOOD CONDITION.

YELLOW AREA DENOTES A BEARING WITH DAMAGE AND REPRESENTS A MARGINAL CONDITION AREA.

RED AREA SIGNIFIES A BEARING WITH DAMAGE IN EXCESS OF THAT WHICH WE FEEL WOULD BE ACCEPTABLE.

NOTE: SPECIFIC LIMITS OF COLORED AREAS COULD CHANGE, DEPENDING ON A GREATER COLLECTION OF DATA.

Fig. 4.4

4.2 42° GEAR BOX

Forty two 42° gear box drive quills (Fig. 4.5) were evaluated. The following graph (Fig. 4.6) and teardown information was taken from a component which was typical of the 42° gear boxes removed for study. The output drive quill of this gear box showed a higher than average rate of shock emissions of approximately 300 and a correspondingly higher level of 200.

The following summary of damage found at teardown correlates with the graphs plotted for the input and output quill assemblies. Figure 4.7 is a photograph of the damaged subassemblies.

PN: 204-04-003-37

SN: #ABB-1101

Two Prior Overhauls

Usage Since New - 1725 hours

Usage Since Overhaul - 148 hours

Input Gear #27427

Pattern low

Input Outer Ball Bearing #56073

Small Pits

Input Inner Ball Bearing #56073

Few pits

Input Roller Bearing #210073

Few pits

Output Gear #27821

Pattern too high and too far towards toe

Output Outer Ball Bearing #56775

Corrosion and pitting throughout bearing


Output Inner Ball Bearing #56775

Corrosion and pitting throughout bearing

Output Roller Bearing #209959

Radial scratches

Figure 4.6 represents a 42° gear box with damage which progressed during a test run. A duplex ball bearing, with a single shallow spall approximately 0.08" x 0.08" in the outer race, was implanted in a 42° gear box. Of particular interest was the observation of progressive damage while the test was in progress. The shape of the shock emission curve changed continuously over a period of minutes in both rate and shock level. The Figure shows two curves developed on a single run. A change in slope takes place (A), a sharp increase in rate (B-C), a continual change in slope (C-D). Without shutting down the engine, the second curve (E-F-G) was developed. After engine shut-down, an oil sample analysis revealed traces of metal, although not beyond that considered acceptable. The dotted line is an extrapolation of the initial slope and gives an indication of the shock level stabilizing at a factor of ten higher. Two more runs were made which essentially repeated curve E-F-G. Teardown analysis showed that the original degradation had not changed noticeably but that new spalls were found on the outer race and on one ball bearing.



42° GEAR BOX QUILL ASSEMBLY
ARROWS DENOTES SENSOR LOCATION




Fig. 4.6



ABB-1101
Output, Outer Bearing,
Corrosion and Pitting
on Outer Race




ABB-1101
Output, Inner Bearing,
Corrosion on Ball



ABB-1101
Output, Inner Bearing,
Corrosion Damage on
Outer Race

Fig. 4.7



42° GEARBOX IMPLANTED WITH A SPALLED DUPLEX BALL BEARING

EVIDENCE OF DAMAGE PROGRESSING

Fig. 4.8

4.3 90° GEAR BOX

Twelve 90° gear boxes (Fig. 4.9) were tested on UH-1 and OH-58 type helicopters. Figure 4.10 is a summary diagram of shock emissions. Two assemblies indicate either a higher rate or higher level than the average of those tested. The curve labeled "damage free" is taken from a gear box of known condition installed on an AIDAPS helicopter at Fort Rucker, Alabama. One of the tested gear boxes was removed for teardown analysis. The principle reason for removing the component was because of the shape and progressing nature of the curve plotted (Fig. 4.11). A curve which, when plotted, develops successively higher x intercepts (levels) is indicative of damage which is progressing. The following data was compiled at the time the gear box was disassembled for analysis:

Photographs of the damaged elements can be seen in Figure 4.12.

FSN: 1615-918-2677

PN: 204-040-012-13

SN: ABC-5688

TSN: 588

TSO: 400

Small Duplex Bearing: PN: 204-040-424-1

SN: 21262

Outer Race: 2 Spalls, Burred Around Edges

Inner Race: 3 Spalls, Evidence of False Brinnelling

Balls: No Apparent Damage

Small Duplex Bearing: PN: 204-040-424-1

SN: 21262

Outer Race: No Apparent Damage

Inner Race: No Apparent Damage

Balls: No Apparent Damage

Small Roller Bearing: PN: 204-040-406-1

SN: 203462

Outer Race: 2 Small Scratches

Inner Race: No Apparent Damage

Rollers: 1 Roller Slightly Scratched

Duplex Bearing: PN: 204-040-143-1

SN: 12620

Outer Race: 1 Small Spall

Inner Race: No Apparent Damage

Cage: No Apparent Damage

Balls: No Apparent Damage

Duplex Bearing: PN: 204-040-143-1

SN: 12620

Outer Race: Mild Corrosion and Pitting

Inner Race: Mild Corrosion and Pitting

Cage: No Apparent Damage

Balls: No Apparent Damage

Roller Bearing: PN: 204-040-407-3


SN: 23475

Outer Race: Mild Pitting, Scratches Parallel to Race

Inner Race: Scratches Parallel to Race


Rollers: No Apparent Damage

The damage found in the outer race of the Small Duplex Bearing SN 21262 is spalling of the nature of sharp burred edges around the spalls. The burred edges would cause the indication apparent in the curve plots.



90° GEAR BOX QUILL ASSEMBLY
ARROW DENOTES SENSOR LOCATION

SUMMARY CHART OF 10 90° GEAR BOX
ASSEMBLIES SHOWING DATA SCATTER



NOTE: Two assemblies showed high rates and levels when compared to the general scatter and a "damage-free assembly".

Fig. 4.10






Fig. 4.11



Small Duplex Bearing
S/N 21262
Outer Race



Small Duplex Bearing
S/N 21262
Inner Race



Duplex Bearing
S/N 12620
Outer Race



Roller Bearing
S/N 23475
Outer Race



Roller Bearing
S/N 23475
Inner Race

4.4 MAST BEARING

Fourteen graphs were plotted on the mast bearing assembly (Fig. 4.13) of UH-1 series helicopter. Figure 4.14 is a scatter diagram of nine different transmissions. The solid line is that recorded from one of the AIDAPS helicopters at Fort Rucker, Alabama. This mast bearing is of known good condition having been inspected prior to its use in the AIDAPS program. The assembly chosen for teardown was the same one which had the highest level and rate of the components tested. The graph (Fig. 4.15) was made over a 40 minute period. After a new bearing was installed, another test was made on the same aircraft with the replacement bearing. New "O" time bearings showed significant reduction in rate and level from the bearing as it was initially tested with the following damage revealed at teardown:

PN. 204-040-136-7-21335

SN. 613m


Outer Race: Scratches parallel to outer race 1 cm
in length, scuffs, false brinnelling
and heat discoloration and corrosion.

Inner Race Ring: Scratches paralalled to race
mild heat discoloration.

Inner Race Ring: Very light scratches and pitting.


Ball and Cage Assembly: Several balls have scratches
and nicks.

Photographs of the damaged elements are shown in Figures 4.16 and 4.17.



MAST BEARING ASSEMBLY
ARROW DENOTES SENSOR LOCATION

Fig. 4.13
-42-



MAST BEARING ASSEMBLY
 ARROW DENOTES SENSOR LOCATION

Fig. 4.13




Fig. 4.14






Fig. 4,15


MAST BEARING
Serial No. 613M



FALSE BRINELLING ON
OUTER RACE




PITTING ON OUTER RACE




SCORING ON BALLS

MAST BEARING
Serial No. 613M




SCORING ON BALLS



NICKS AND SCRATCHES
ON INNER RACE

4.5 TRANSMISSION INPUT DRIVE QUILL

Thirteen input drive quills (Fig. 4.18) were tested on UH-1 series helicopters. One of the assemblies tested had relatively high rate and levels of shock emissions, however, the transmission was not removed for teardown due to the time and expense involved. Figure 4.19 presents the data scatter of all input quill assemblies tested including the suspect component. Again the curve label "damage-free" was taken from a helicopter in the AIDAPS program.



-48- Fig. 4.18





Fig. 4.19

5.0 FLIGHT TESTS DATA

Although not a contractual requirement, data was collected with the MEPA 10A under conditions other than ground runs. Figure 5.0 shows a comparison of ground, hover-in-ground effect, low and high speed flight and autorotation conditions. All data collected was from the input drive quill of the transmission. This component was selected because the ease of accelerometer mounting and security of cables from moving and rotating assemblies. Figure 5.1 compares two UH-1H helicopters at the same "high speed" flight condition. The various flight conditions had negligible effect on the shape of the shock emission envelope. Flight data fell well within the scatter of the bulk of data tested for the input quill. More testing would be required before advancing any conclusions as to optimum sensor location or flight profiles necessary for a test program.



$N_2 = 6600$ rpm Altitude 3000 ft.




Fig. 5.1

6.0 RESULTS AND CONCLUSIONS

The SKF MEPA-10A has shown its effectiveness and reliability as a bearing analyzer. The shock pulse technique has proven its values as a quick and accurate means to determine the general health of a component by plotting the shock emission profile of non-friction bearings. When components were tested and reviewed in comparison with others of the same type, it becomes apparent that the shock pulse technique can separate assemblies by degree's of damage. However, it was not possible to localize the damage as to the rolling elements, inner or outer race, etc. All of the damage which was revealed at tear-down was correlatable to the data plotted from shock emissions.

In over 150 studies conducted on assemblies with the shock pulse technique, the MEPA-10A did not have any malfunctions. The conditions which prevailed during field testing ranged from approximately -30°C to $+40^{\circ}\text{C}$ (-14°F to 104°F) and relative humidity from 30% to 100%. Accelerometers were exposed to exhaust gas temperatures in excess of 200°C and the g forces associated with flight, without failure. Some difficulty was experienced with cables and fittings although not of a significant nature. A recommended ongoing program of flight tests will require some hardware refinement to insure system reliability in a flight environment.

Several assemblies which contain antifriction bearings were analyzed to insure the feasibility of data collection on all aircraft components regardless of bearing size or rotational speed. The only limiting factor to the shock pulse technique is that the accelerometer be located either on the bearing fixture or at a location with a direct mechanical path

to the bearing. With few exceptions all the assemblies on a helicopter can be rapidly and effectively analyzed.

Efforts to realize a method of diagnostics for gear analysis proved to be of value in determining the possible existence of foreign particulate matter in the lubricant of a gear box. If the damage present on a set of gears is the type that debris will result from tooth contact, then the shock pulse method appears to have the ability to show damage by evaluating the particulate matter as it passes in transient through a bearing assembly.

REFERENCES

1. James Provenzano, John Games, Al Wyrostek, Art Ostheimer, Jack Young, "UH-1H AIDAPS Test Bed Program," Vol. I and II; USAAVSCOM Technical Report 72-18, Aug. 1972.
2. Robert R. Butcher, Russel Kirby, Jr., John Nakakihara, T.C. Watkins, "UH-1H Test Bed Program," Vol. I and II; USAAVSCOM Technical Report 72-19, June 1972.
3. John A. George, Richard M. Andres, J. Thomas Harrington, "Parks College UH-1H AIDAPS Program," Parks College of Saint Louis University, Final Report, Jan. 1975.
4. "AIDAPS Development Program, 2nd Interim Report," USAAVSCOM Technical Report 74-50, Nov. 1974.
5. Edward F. Covill, Timothy C. Mayer, John A. George, "Preliminary Evaluation of the Shock Pulse Technique to the UH-1 Series Helicopter," Parks College of Saint Louis University, Jan. 1974.
6. Timothy C. Mayer, Edward F. Covill, John A. George, J. Thomas Harrington, "Field Evaluation Of the Shock Pulse Technique to the UH-1 Series Helicopter," Parks College of Saint Louis University, June 1974.
7. John A. George, Timothy C. Mayer, Edward F. Covill, "Evaluation of the Shock Pulse Technique to the UH-1 Series Helicopter," 45th Shock and Vibration Symposium, Dayton, Ohio, Oct. 1974.
8. Timothy C. Mayer, Edward F. Covill, John A. George, "Shock Pulse Meter Analysis," Parks College of Saint Louis University, Oct. 1974.

F I N A L R E P O R T

APPLICATIONS OF THE SHOCK PULSE
TECHNIQUE TO HELICOPTER DIAGNOSTICS

PART II

TIMOTHY C. MAYER
EDWARD F. COVILL
JOHN A. GEORGE
J. THOMAS HARRINGTON

PARKS COLLEGE OF SAINT LOUIS UNIVERSITY
CAHOKIA, ILLINOIS
FEBRUARY 24, 1975

BOA DAAJ01-72-A-0027 (P6C)
DO DAAJ01-72-A-0027-0001 (P6C)
DO DAAJ01-72-A-0027-0002 (P6C)

7.0 TABLES AND APPENDICES

The following section is a compilation of all data gathered to date. The data is arranged in order to provide readability with the report.

CONTENTS

- 7.1 Tables
- 7.2 Initial Familiarization and Laboratory Tests
- 7.3 Accelerometer Mounts
- 7.4 Field Data (local)
- 7.5 Field Data (Ft. Rucker)
- 7.6 Damaged Gears
- 7.7 SKF Report
- 7.8 Statistical Summary of Shock Pulse Data

7.1 TABLES

Aircraft #	Type	Position	Serial #	TSN	Hours	Comment	Date	Rate	Level
13740	UH-1H	42° Gearbox Input Quill	AB-1097				Nov. 27, 1973	100	65
13740	UH-1H	42° Gearbox Output Quill	AB-1097				Nov. 27, 1973	75	55
16197	UH-1H	42° Gearbox Input Quill	BBB-289		225		Nov. 27, 1973	150	80
16197	UH-1H	42° Gearbox Output Quill	BBB-289		225		Nov. 27, 1973	85	80
66-01087	UH-1H	42° Gearbox Input Quill	B13-3886		727		Nov. 28, 1973	150	70
15949	UH-1H	42° Gearbox Input Quill	B13-5346				Nov. 28, 1973	150	110
15949	UH-1H	42° Gearbox Output Quill	B13-5346				Nov. 28, 1973	75	110
59519	UH-1M	42° Gearbox Input Quill	ABB-1742				Nov. 30, 1973	220	50
59519	UH-1M	42° Gearbox Output Quill	ABB-1742				Nov. 30, 1973	200	40
15200	UH-1M	42° Gearbox Input Quill	ABB-6012	298	298		Dec. 6, 1973	600	200
15200	UH-1M	42° Gearbox Output Quill	ABB-6012	298	298		Dec. 6, 1973	110	150
69-15771	UH-1H	42° Gearbox Input Quill	ABB-2667		1042	Excessive Needle Swing *	Dec. 6, 1973	300	150
69-15771	UH-1H	42° Gearbox Output Quill	ABB-2667			Excessive Needle Swing *	Dec. 6, 1973	250	300
66-15190	UH-1M	42° Gearbox Input Quill	AB-1101		148	Excessive Needle Swing *	Dec. 12, 1973	250	90
66-15190	UH-1M	42° Gearbox Output Quill	AB-1101		148	Excessive Needle Swing *	Dec. 12, 1973	300	195
66-16879	UH-1H	42° Gearbox Output Quill	B13-3800		569	Excessive Needle Swing *	Dec. 13, 1973	500	195
BC14	UH-1H	42° Gearbox Input Quill	B13-9881			Data Scatter 3 Runs	June 13, 1974	140/190	100/160
BC13	UH-1H	42° Gearbox	B13-4312				June 13, 1974	75	50
BC13	UH-1H	42° Gearbox Input Quill	B13-8282				June 14, 1974	200	700
BC14	UH-1H	42° Gearbox					June 14, 1974	200	70
BC14	UH-1H	42° Gearbox					June 14, 1974	25	80

* Removed for Analysis

Aircraft #	Type	Position	Serial #	TSN	Hours TSO	Comment	Date	Rate	Level
BC14	UH-1H	42° Gearbox					June 14, 1974	175	30
15550	UH-1H	42° Gearbox Output Quill	B13-2929	1324	New		July 30, 1974	25	80
15550	UH-1H	42° Gearbox Input Quill	B13-2929	1324	New		July 30, 1974	100	90
13740	UH-1H	42° Gearbox Output Quill	A13-1097	173	0		July 31, 1974	75	60
13740	UH-1H	42° Gearbox Input Quill	A13-1097	173	0		July 31, 1974	75	60
60529	UH-1H	42° Gearbox Output Quill	A13-1639	75	0		Aug. 1, 1974	350	320
60529	UH-1M	42° Gearbox Input Quill	A13-1639	75	0		Aug. 1, 1974	35	75
15200	UH-1M	42° Gearbox Output Quill	B13-8818	24	0		Aug. 1, 1974	150	30
15200	UH-1M	42° Gearbox Input Quill	B13-8818	24	0		Aug. 1, 1974	40	80
59884	UH-1D	42° Gearbox Input Quill	B13-9384		626		Aug. 5, 1974	25	80
60630	UH-1C	42° Gearbox Output Quill	B13-3243	1735	939	*	Aug. 6, 1974	625	300
60630	UH-1C	42° Gearbox Input Quill	B13-3243	1735	939	*	Aug. 6, 1974	100	40
15071	UH-1C	42° Gearbox Input Quill					Aug. 6, 1974	85	50
15071	UH-1C	42° Gearbox Output Quill	BBB-1894		237		Aug. 6, 1974	80	80
59519	UH-1M	42° Gearbox Input Quill	ABB-742		171		Aug. 8, 1974	110	43
59519	UH-1M	42° Gearbox Output Quill	ABB-742		171		Aug. 8, 1974	100	40
15091	UH-1M	42° Gearbox Input Quill	B-13-646				Aug. 9, 1974	30	40
16354	UH-1H	42° Gearbox Input Quill	B13-6564				Aug. 12, 1974	35	60
16354	UH-1H	42° Gearbox Output Quill	B13-6564				Aug. 12, 1974	150	320
16779	UH-1D	42° Gearbox Output Quill	B13-6509				Aug. 14, 1974	100	75
16779	UH-1D	42° Gearbox Input Quill	B13-6509				Aug. 14, 1974	10	40

* Removed for Analysis

Aircraft #	Type	Position	Serial #	TSN	Hours TSN	Comment	Date	Rate	Level
16264	UH-1H	#3 Hanger Bearing	A20-67523	806		Removed *	Nov.13,1973	340	600
16264	UH-1H	#4 Hanger Bearing	A20-60933				Nov.13,1973	100	85
59771	UH-1D	#3 Hanger Bearing	A20-69969				Nov.14,1973	185	90
59771	UH-1D	#4 Hanger Bearing	A20-23720				Nov.14,1973	150	65
13740	UH-1H	#3 Hanger Bearing	A20-27256				Nov.14,1973	100	45
13740	UH-1H	#4 Hanger Bearing	A20-44738		306		Nov.14,1973	150	52
16264	UH-1H	#3 Hanger Bearing	A20-55994			new bearing (replacement)	Nov.19,1973	175	95
16197	UH-1H	#3 Hanger Bearing	A20-48180		225		Nov.27,1973	240	110
16197	UH-1H	#4 Hanger Bearing	A20-19152		225		Nov.27,1973	120	70
13740	UH-1H	#3 Hanger Bearing	A20-27256			repeat hanger 11/14/73	Nov.27,1973	150	45
13740	UH-1H	#4 Hanger Bearing	A20-44738			repeat hanger 11/14/73	Nov.27,1973	100	60
66-01087	UH-1H	#3 Hanger Bearing	A20-43391		488	Removed *	Nov.28,1973	300	900
66-01087	UH-1H	#4 Hanger Bearing	A20-37362		501	Aircraft *	Nov.28,1973	300	45
66-01087	UH-1H	#4 Hanger Bearing	A20-37362		501	Laboratory *	Nov.28,1973	65	170
15949	UH-1H	#3 Hanger Bearing	A20-64495		427	Removed *	Nov.28,1973	150	1800
15949	UH-1H	#4 Hanger Bearing	A20-64906		427	Removed *	Nov.28,1973	295	550
59519	UH-1M	#1 Hanger Bearing	A20-44891				Nov.30,1973	95	700
59519	UH-1M	#2 Hanger Bearing	A20-57910				Nov.30,1973	150	200
59519	UH-1M	#3 Hanger Bearing	A20-11446			Removed-Ex- cessive Needle Swing *	Nov.30.;973	300	1200
66-01087	UH-1H	#3 Hanger Bearing	A20-10705			new bearing (replacement)	Nov.30,1973	200	80
15949	UH-1H	#3 Hanger Bearing				new bearing (replacement)	Nov.30,1973	200	70

* Removed for Analysis

Aircraft #	Type	Position	Serial #	TSN	Hours	TSO	Comment	Date	Rate	Level
15949	UH-1H	#4 Hanger Bearing					New bearing (replacement)	Nov. 30, 1973	320	50
15200	UH-1M	#1 Hanger Bearing	A20-29105			143		Dec. 6, 1973	170	60
15200	UH-1M	#2 Hanger Bearing	A20-22817			143		Dec. 6, 1973	55	50
15200	UH-1M	#3 Hanger Bearing	A20-10877			143		Dec. 6, 1973	185	50
66-15190	UH-1M	#1 Hanger Bearing	A20-56617			80		Dec. 12, 1973	200	400
66-15190	UH-1M	#2 Hanger Bearing	A20-46146			80		Dec. 12, 1973	100	150
66-15190	UH-1M	#3 Hanger Bearing	A20-53737			80		Dec. 12, 1973	60	55
66-16879	UH-1H	#3 Hanger Bearing	A20-26745			403	Removed for Analysis *	Dec. 12, 1973	250	2500
66-16879	UH-1H	#4 Hanger Bearing	A20-31225			403	Removed for Analysis *	Dec. 12, 1973	300	6000
38784	UH-1H	#3 Hanger Bearing	A20-36705	1166		646	6600 *	May 21, 1974	150	1500
38784	UH-1H	#3 Hanger Bearing	A20-36705				4600	May 21, 1974	80	1000
38484	UH-1H	#4 Hanger Bearing	A20-31435				4600	May 21, 1974	225	4800
38784	UH-1H	#4 Hanger Bearing	A20-31435				6600 *	May 21, 1974	225	7000
BC14	UH-1H	#3 Hanger Bearing					Left Pedal	June 13, 1974	35	65
BC14	UH-1H	#4 Hanger Bearing					Left Pedal	June 13, 1974	300	1000
BC14	UH-1H	#4 Hanger Bearing					Right Pedal	June 13, 1974	300	1000
BC14	UH-1H	#4 Hanger Bearing					Neutral Pedal	June 13, 1974	300	700
BC13	UH-1H	#4 Hanger Bearing	A20-34779					June 13, 1974	120	100
BC13	UH-1H	#3 Hanger Bearing						June 13, 1974	45	150
BC14	UH-1H	#4 Hanger Bearing					Flight Idle	June 13, 1974	220	200
BC14	UH-1H	#4 Hanger Bearing					6400 Full Rt. Pedal	June 13, 1974	240	900


* Removed for Analysis

Aircraft #	Type	Position	Serial #	TSN	Hours TSO	Comment	Date	Rate	Level
BC14	UH-1H	#3 Hanger Bearing				Flight Idle	June 13, 1974	150	25
BC14	UH-1H	#3 Hanger Bearing				6400	June 13, 1974	90	50
BC13	UH-1H	Hanger Bearing				Full Rt. Pedal Damage Free Assy	June 14, 1974	100	50
BC13	UH-1H	#3 Hanger Bearing					June 14, 1974	65	150
13740	UH-1H	#3 Hanger Bearing					July 31, 1974	120	60
13740	UH-1H	#4 Hanger Bearing					July 31, 1974	140	30
60529	UH-1M	#3 Hanger Bearing	A20-64529	75	0	*	Aug. 1, 1974	400	800
60529	UH-1M	#2 Hanger Bearing	A20-52529		0		Aug. 1, 1974	250	80
15200	UH-1M	#3 Hanger Bearing			167		Aug. 1, 1974	130	50
15200	UH-1M	#2 Hanger Bearing			167		Aug. 1, 1974	300	80
15200	UH-1M	#1 Hanger Bearing			167		Aug. 1, 1974	340	160
59884	UH-1D	#3 Hanger Bearing					Aug. 5, 1974	150	20
60630	UH-1C	#1 Hanger Bearing					Aug. 6, 1974	300	70
15071	UH-1C	#3 Hanger Bearing					Aug. 6, 1974	320	850
60630	UH-1C	#3 Hanger Bearing					Aug. 6, 1974	160	150
60630	UH-1C	#2 Hanger Bearing					Aug. 6, 1974	100	40
15071	UH-1C	#2 Hanger Bearing	A20-15990		237	*	Aug. 6, 1974	300	3000
15071	UH-1C	#1 Hanger Bearing	A20-66943		237		Aug. 6, 1974	65	50
59519	UH-1M	#2 Hanger Bearing	A20-57910		171		Aug. 8, 1974	120	70
59519	UH-1M	#3 Hanger Bearing	A20-26938		27		Aug. 8, 1974	150	50
59519	UH-1M	#1 Hanger Bearing	A20-44891	2219	194		Aug. 8, 1974	340	700

* Removed for Analysis


7.2 INITIAL FAMILIARIZATION AND LABORATORY TESTS

INITIAL FAMILIARIZATION ON THE NUMBER FOUR
HANGER BEARING OF AIRCRAFT UH-1H, 67-17223




BEARING APPEARS IN GOOD CONDITION WITH
MODERATE TO LOW RATE/POTENTIOMETER LEVELS

INITIAL FAMILIARIZATION ON NUMBER THREE
 HANGER BEARING OF AIRCRAFT UH-1H, 67-17223




BEARING APPEARS IN GOOD CONDITION WITH
 MODERATE TO LOW RATE/POTENTIOMETER LEVELS

ADDITIONAL FAMILIARIZATION ON THE NUMBER THREE HANGER BEARING
OF AIRCRAFT UH-1H, 67-17223 TEST PERFORMED ON THE SAME
BEARING AS DEPICTED IN FIG. 5 BUT PERFORMED BY ANOTHER INDIVIDUAL




PLOT SHOWS BASIC SIMILARITY AND LEVEL PORTRAYALS
EVEN THOUGH THEY WERE PERFORMED BY TWO DIFFERENT PEOPLE

INITIAL FAMILIARIZATION ON THE OUTPUT DRIVE QUILL
BEARING OF THE 42° GEAR BOX OF AIRCRAFT UH-1H, 67-17223




MODERATE LEVELS OF RATE/POTENTIOMETER DEPICTION
INDICATIVE OF BEARING IN GOOD CONDITION

INITIAL FAMILIARIZATION ON THE NUMBER ONE
HANGER BEARING OF AIRCRAFT UH-1H, 67-17223



BEARING APPEARS IN GOOD CONDITION
WITH MODERATE TO LOW RATE/POTENTIOMETER LEVELS

TEST OF BEARING USED ON THE TAIL ROTOR STIKE TEST PERFORMED BY
BAGANOFF INDUSTRIES TO DETERMINE CONDITION FOR LATER AIRCRAFT USE
TEST PERFORMED ON AIRCRAFT UH-1H, 66-17138




BEARING APPEARS IN GOOD CONDITION WITH
ONLY MODERATE RATE/POTENTIOMETER LEVELS

TEST PERFORMED WITH BEARING IN THE NUMBER THREE HANGER POSITION


TEST ON BEARING WHICH WAS DESCRIBED AS BEING REMOVED BECAUSE
OF 600 HOUR TIME CHANGE ON UNSERVICEABLE TAG-MATERIAL

BEARING APPEARS TO STILL BE IN SERVICEABLE CONDITION AND
RATE/POTENTIOMETER LEVELS DO NOT INDICATE TOO HIGH FOR USE



TEST PERFORMED ON BEARING IN THE
NUMBER THREE HANGER POSITION


THIS GRAPH DEPICTS THE BEARING USED IN CONJUNCTION
WITH A BEARING TEST BY BAGANOFF ASSOCIATES



THE BEARING DEPICTED WAS ONE WITH OBVIOUS DAMAGE AND IN AN
UNSERVICEABLE CONDITION LISTED AS "ROUGH AND DRY".

THREE CURVES WERE PLOTTED ON THE SAME BEARING, ALL OF WHICH
SHOW CLEARLY THE DAMAGE IN THE HIGH POTENTIOMETER LEVELS, WHICH IN
SOME CASES SEEMED TO EXTEND TO INFINITY, INDICATIVE OF SEVERE ROLLING ELEMENT DAMAGE.


THIS GRAPH DEPICTS THE BEARING USED IN CONJUNCTION
WITH A BEARING TEST BY BAGANOFF ASSOCIATES



THE BEARING DEPICTED WAS ONE WITH OBVIOUS DAMAGE AND IN AN
UNSERVICEABLE CONDITION LISTED AS "ROUGH AND DRY".

THREE CURVES WERE PLOTTED ON THE SAME BEARING, ALL OF WHICH
SHOW CLEARLY THE DAMAGE IN THE HIGH POTENTIOMETER LEVELS, WHICH IN
SOME CASES SEEMED TO EXTEND TO SEVERE ROLLING ELEMENT DAMAGE.


FLIGHT TEST ON THE OUTPUT DRIVE QUILL OF THE
42° GEAR BOX OF AIRCRAFT UH-1H, 66-17138



TEST CONDUCTED AT HOVER IN-GROUND EFFECT.
TORQUE VALUE OF 30 PSI AND N1 VALUE OF 92.8%, 6600 ENGINE RPM


(NOTE HIGH POTENTIOMETER LEVEL OF 190 WHEN COMPARED TO 42° GEAR
BOX TEST WHEN NOT CONFIGURED FOR FLIGHT TEST)

HOVER CONDITION IN GROUND AFFECT



THIS SERIES OF GRAPHS WERE MADE FROM DATA COLLECTED IN FLIGHT CONDITIONS ON AIRCRAFT UH-1H, 67-17223. ALL OF THE DATA WAS TAKEN AT THE OUTPUT DRIVE QUILL AND CAN BE COMPARED TO PREVIOUS GRAPHS OF THE SAME BEARING ELEMENT.


FLIGHT CONDITIONS OF 75 KNOTS AT 22 LBS. TORQUE



THIS SERIES OF GRAPHS WERE MADE FROM DATA COLLECTED IN FLIGHT CONDITIONS ON AIRCRAFT UH-1H, 67-17223. ALL OF THE DATA WAS TAKEN AT THE OUTPUT DRIVE QUILL AND CAN BE COMPARED TO PREVIOUS GRAPHS OF THE SAME BEARING ELEMENT.


FLIGHT TEST CONDUCTED AT LOW FLIGHT SPEED
(APPROX. 88 kts) AT TORQUE VALUE OF 25 psi AND
91.0% ni, 6600 ENGINE RPM

TEST PERFORMED ON 42° GEAR BOX OUTPUT DRIVE
Rate QUILL BEARING OF AIRCRAFT UH-1H, 66-17138




(NOTE, POTENTIOMETER LEVEL IS APPROXIMATELY THE SAME
AS IN HOVER TEST OF THE SAME BEARING PACKAGE, HOWEVER, THE
RATE LEVEL HAS INCREASED SIGNIFICANTLY)

FLIGHT CONDITIONS OF 95 KNOTS AT 25 LBS. TORQUE



THIS SERIES OF GRAPHS WERE MADE FROM DATA COLLECTED IN FLIGHT CONDITIONS ON AIRCRAFT UH-1H, 67-17223. ALL OF THE DATA WAS TAKEN AT THE OUTPUT DRIVE QUILL AND CAN BE COMPARED TO PREVIOUS GRAPHS OF THE SAME BEARING ELEMENT.


TEST PLOT WITH CABLE OUTSIDE AIRCRAFT UH-1H
66-17138 ON 42° GEAR BOX OUTPUT QUILL BEARING



THIS GRAPH DEPICTS A REFERENCE TEST MADE TO ONLY THE MEPA 10-A BEARING ANALYZER IN ITS CONFIGURATION USED FOR FLIGHT TESTING, THE REASON FOR THIS TEST WAS TO DETERMINE TO WHAT EXTENT THE CABLE INSTALLATION INSIDE THE TAIL BOOM MADE, IF ANY

THE CONCLUSION DRAWN AT THIS TIME IS THAT ITS INSTALLATION INSIDE OR OUT YIELDED THE SAME CURVE FORM


TEST PERFORMED ON THE 42° GEAR BOX
OF AIRCRAFT, UH-1H 66-17138




THIS TEST UTILIZED THE SAME MOUNTING BRACKET AS THAT USED ON THE FLIGHT TESTS ON THE BEARING ANALYZER, HOWEVER, THE CABLE WHICH CAME WITH THE SKF BEARING ANALYZER WAS USED IN LIEU OF THE CABLE CONFIGURATION EMPLOYED FOR FLIGHT TESTING

THE CURVE DEPICTS THE SAME SHAPE AS IN THE FLIGHT CONFIGURATION TESTING, HOWEVER, IN FLIGHT CONFIGURATION THE RATE/POTENTIOMETER IS APPROXIMATELY TRIPLED


NORMALIZATION CURVE NEW BEARING





a)



b)



FOREIGN MATTER IN BEARING LUBRICATION



AD-A040 130


PARKS COLL OF SAINT LOUIS UNIV CAHOKIA ILL
APPLICATIONS OF THE SHOCK PULSE TECHNIQUE TO HELICOPTER DIAGNOS--ETC(U)
FEB 75 T C MAYER, E F COVILL, J A GEORGE
DAAJ01-72-A-0027
USAAVSCOM-TR-77-21 NL

UNCLASSIFIED

2 OF 3


AD
A040 130






MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

NORMALIZATION CURVE NEW BEARING




a)



b)




DRY BEARING




a)

b)

NORMALIZATION CURVE NEW BEARING





a.)




b.)




INNER RACE DAMAGES



NORMALIZATION CURVE NEW BEARING




a)




b)



OUTER RACE DAMAGES




a)



b)




NORMALIZATION CURVE NEW BEARING




a)


b)



ROLLING ELEMENT DAMAGE



a)




b)



START OF TIME TEST

FIGS. 3.6A - 3.6D SHOWS BEARING WITH SEVERE DAMAGE TO INNER RACE, SHOCK READINGS TAKEN AT INTERVALS OF 30, 60 and 100 MIN. ACCELEROMETER ATTACHMENT WITH VICE GRIPS AND 3750 RPM




a)



Oscilloscope sweep at 20 milliseconds only. quantity not amplitude of shock emission can be considered.


b)





Each curve represents one revolution.


39

AFTER 30 MIN. RUNNING TIME



- a)  Oscilloscope sweep at 20 milliseconds only quantity not amplitude of shock emission can be considered.
- b)  Each curve represents one revolution.

AFTER 60 MIN. RUNNING TIME




a)




Oscilloscope sweep at 20 milliseconds only quantity not amplitude of shock emission can be considered.

b)



Each curve represents one revolution.

CONCLUDING READING AFTER 100 MIN. RUNNING TIME




a)




Oscilloscope sweep at 20 milliseconds only quantity not amplitude of shock emission can be considered.

b)



Each curve represents one revolution.

FIGS. 3.7a AND 3.7b DEPICTS THE SAME BEARING WITH IDENTICAL ACCELEROMETER ATTACHMENT RUN AT 2520 AND 3750 RPM'S RESPECTIVELY. RPM INCREASED APPROXIMATELY 50% AND IN THIS INSTANCE BOTH RATE AND LEVEL INCREASED WITH THE RPM INCREASE AS GRAPHED.






a)


b)

43


DIRTY LUBRICANT 3750 RPM




NEW BEARING





a)




b)



ROLLING ELEMENT DAMAGE






DIRTY LUBRICANT




a)

b)

DRY BEARING




VARIATIONS OF ACCELEROMETER ATTACHMENT



BEARING WITH BALL DAMAGE.


FOUR DIFFERENT METHODS OF ACCELEROMETER ATTACHMENT ON THE SAME BEARING RUN AT A CONSTANT RPM. (3700) THE RATES VARY LESS THAN POTENTIOMETER LEVELS WHICH VARY BETWEEN 200 and 9000.


NEEDLE SWING ERROR IN INITIAL RATE PLOT



7.3 ACCELEROMETER MOUNTS


VICE GRIP ACCELEROMETER MOUNT





VD-1 accelerometer mount.

Accelerometer mounts VD-3 thru VD-5 differ from the pictured mounts in the dimensions of the aperture of the fixture that fits over the lands of the nuts in the bearing assembly. The sizes of nuts which can be accommodated with the VD 1-5 are 5/16, 3/8, 7/16, 9/16 with the VD-2 affixed to the washers used on the mounting bolts of a bearing fixture.




VD-2 accelerometer mount.

7.4 FIELD DATA (local)

NUMBER 3 HANGER BEARING UH-1H

TAIL #16264

TEST CONDUCTED 13 NOV 1973 AT BI STATE AIRPORT




BEARING SERIAL #A20-67523 REMOVED FOR PHYSICAL ANALYSIS.

NUMBER 4 HANGER BEARING

UH-1H TAIL #16264


TEST CONDUCTED 13 NOV 1973 AT BI-STATE AIRPORT



NUMBER 3 HANGER BEARING

UH-1D TAIL #59771


TEST CONDUCTED 14 NOV 1973 AT BI-STATE AIRPORT



NUMBER 4 HANGER BEARING

UH-1D TAIL #59771


TEST CONDUCTED 14 NOV 1973 AT BI-STATE AIRPORT



NUMBER 3 HANGER BEARING

UH-1H TAIL #13740


TEST CONDUCTED 14 NOV 1973 AT BI-STATE AIRPORT



NUMBER 4 HANGER BEARING

UH-1H TAIL #13740


TEST CONDUCTED 14 NOV 1973 AT BI-STATE AIRPORT



NUMBER 3 HANGER BEARING UH-1H

TAIL #16264

TEST CONDUCTED 19 NOV 1973 AT BI STATE AIRPORT




REPEAT OF #3 HANGER BEARING POSITION AFTER INSTALLATION OF NEW BEARING.

NUMBER 3 HANGER BEARING

UH-1H TAIL #16197


TEST CONDUCTED 27 NOV 1973 AT SCOTT AFB




NUMBER 4 HANGER BEARING

UH-1H TAIL #16197

TEST CONDUCTED 27 NOV 1973 AT SCOTT AFB






NUMBER 4 HANGER BEARING UH-1H

TAIL #13740

TEST CONDUCTED 27 NOV 1973 AT SCOTT AFB




NUMBER 3 HANGER BEARING UH-1H

TAIL #66-01087

TEST CONDUCTED 28 NOV 1973 AT SCOTT AFB

BEARING SERIAL #A20-43391




REMOVED FOR ANALYSIS, EXCESSIVE POTENTIOMETER LEVEL RESTRAINING HIGH RATES.

4 HANGER BEARINGS

UH-1H TAIL #66-01087

TEST CONDUCTED 28 NOV 1973




GRAPH OF BEARING #A2037362 WHICH WAS REMOVED FOR ANALYSIS BECAUSE OF EXCESSIVE PLAY DISCOVERED BY AN AIRCRAFT TECHNICAL INSPECTOR - ONE GRAPH MADE ON AIRCRAFT, THE OTHER IN LABORATORY AT APPROXIMATELY THE SAME RPM. (14 DEC 1973).

NUMBER 3 HANGER BEARING UH-1H

TAIL #15949

TEST CONDUCTED 28 NOV 1973 AT SCOTT AFB




BEARING SERIAL #A20-64495 REMOVED FOR PHYSICAL ANALYSIS/EXCESSIVE POTENTIOMETER LEVELS NORMAL RATES OF SHOCK.

NUMBER 4 HANGER BEARING UH-1H

TAIL # 15949

TEST CONDUCTED 28 NOV 1973 AT SCOTT AFB




BEARING SERIAL #A20-64906 REMOVED FOR PHYSICAL ANALYSIS/EXCESSIVE POTENTIOMETER LEVELS.

NUMBER 1 HANGER BEARING

UH-1M TAIL #59519

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB




RATE APPEARED LESS THAN NORMAL WITH POTENTIOMETER LEVEL IN EXCESS OF NORMAL. BEARING WAS NOT REMOVED FOR PHYSICAL ANALYSIS.

NUMBER 2 HANGER BEARING

UH-1M TAIL #59519

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB




NUMBER 3 HANGER BEARING

UH-1M TAIL #59519

BEARING SERIAL #A20-11446

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB




SHADED AREA REPRESENTS EXCESSIVE NEEDLE SWING ON MEPA-10A - BEARING REMOVED FOR ANALYSIS.

NUMBER 3 HANGER BEARING (NEW BEARING)

UH-1H TAIL #66-1087

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB




TEST IS A REPEAT OF TEST MADE ON 28 NOV 1973 OF NUMBER 3 HANGER BEARING OF THE SAME AIRCRAFT WHICH WAS REMOVED FOR TEAR DOWN ANALYSIS.

NUMBER 3 HANGER BEARING UH-1H (NEW BEARING)

TAIL #15949

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB




REPEAT OF TEST CONDUCTED 28 NOV 1973 ON #3 HANGER BEARING WHICH WAS REMOVED FOR PHYSICAL ANALYSIS.

NUMBER 4 HANGER BEARING UH-1H (NEW BEARING)

TAIL #15949

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB




REPEAT OF TEST CONDUCTED 28 NOV 1973 ON #4 HANGER BEARING WHICH WAS REMOVED FOR PHYSICAL ANALYSIS.

NUMBER 1 HANGER BEARING

UH-1M TAIL #15200


TEST CONDUCTED 6 DEC 1973 AT SCOTT AFB



NUMBER 2 HANGER BEARING

UH-1M TAIL #15200


TEST CONDUCTED 6 DEC 1973 AT SCOTT AFB



NUMBER 3 HANGER BEARING

UH-1M TAIL #15200


TEST CONDUCTED 6 DEC 1973 AT SCOTT AFB



NUMBER 1 HANGER BEARING

UH-1M TAIL #66-15190

TEST CONDUCTED 12 DEC 1973 AT BI-STATE AIRPORT




BEARING DEPICTS CURVE ABOVE NORMAL BUT A CONSIDERATION OF DAMAGE EVIDENCE IN TEARDOWN INSPECTION MUST BE MADE PRIOR TO A DETERMINATION THIS BEARING IS EXCESSIVELY DAMAGED.

NUMBER 2 HANGER BEARING

UH-1M TAIL #66-15190

TEST CONDUCTED 12 DEC 1973 AT BI-STATE AIRPORT




BEARING SHOWED NORMAL RATE AND VALUE.

NUMBER 3 HANGER BEARING

UH-1M TAIL #66-15190

TEST CONDUCTED 12 DEC 1973 AT BI-STATE AIRPORT




BEARING SHOWED NORMAL RATE AND VALUE.

NUMBER 3 HANGER BEARING

UH-1H TAIL #66-16879

BEARING SERIAL #A20-26745

TEST CONDUCTED 12 DEC 1973 AT BI-STATE AIRPORT




RATE OF 250 AND VALUE OF 2500
BEARING REMOVED FOR ANALYSIS

NUMBER 4 HANGER BEARING

UH-1H TAIL #66-16879

BEARING SERIAL #A20-31225

TEST CONDUCTED 12 DEC 1973 AT RI-STATE AIRPORT



RATE OF 300 AND VALUE IN EXCESS OF 6,000
BEARING REMOVED FOR ANALYSIS


21 May 74

#3 Hanger Bearing



SN A20-36705

A/C 63-8784

6600 RPM N₂




NOTE: ----- 4600 RPM
 _____ 6600 RPM



Hanger Bearing
S/N A20-36705
A/C 63-8784

4 Hanger Bearing

SN A20-31435

A/C 63-8784
6600 RPM N₂

NOTE: _____ 6600
----- 4600




Hanger Bearing
S/N A20-31435
A/C 63-8784

31 Jul 74

#3 Hanger Bearing


#4 Hanger Bearing

A/C 64-13740 UH-1H
6600 RPM N_2 

NOTE: #3 Hanger Bearing-----
#4 Hanger Bearing_____

#3 Hanger Bearing

A/C 66-15200 UH-1M
6600 RPM N₂



NOTE: #1 Hanger Bearing _____
#2 Hanger Bearing - - - - -
#3 Hanger Bearing _____

#3 Hanger Bearing A20-26938

6600 RPM N_2

Rate


Integration time seconds:

Potentiometer level

NOTE: #1 Hanger Bearing _____
 #2 Hanger Bearing - - - - -
 #3 Hanger Bearing - . - . - .

9 Aug 74


#1 Hanger Bearing

A/C UH-1M 66-15091
6600 RPM N_2 


NOTE: ...#1 Hanger Bearing

#3 Hanger Bearing A20-64529

#2 Hanger Bearing A20-52529

A/C 66-0529 UH-1M
6600 RPM N₂NOTE: #3 Hanger Bearing _____
#2 Hanger Bearing - - - - -

#3 Hanger Bearing A20-43493


A/C 65-9884 UH-1D
6600 RPM N₂

NOTE: #3 Hanger Bearing _____

6 Aug 74

#2 Hanger Bearing


#3 Hanger Bearing

A/C UH-1C 60630
6600 RPM N₂


NOTE: #2 Hanger Bearing -----
#3 Hanger Bearing _____

#1 Hanger Bearing
#2 Hanger Bearing A20-15990
#3 Hanger Bearing A20-31517

A/C 66-15071 UH-1C
6600 RPM N₂




#1 Hanger Bearing

A/C UH-1C 60630
6600 RPM N₂

NOTE: #1 Hanger Bearing _____

23 Sept 74

#1 Hanger Bearing
SN A20-55389A/C 69-15949
6600 RPM N₂




Hanger Bearing
 P/N A20-55389
 A/C 69-15949

42° GEARBOX

UH-1H TAIL #13740

TEST CONDUCTED 27 NOV 1973 AT SCOTT AFB




ONE CURVE DEPICTS INPUT DRIVE QUILL, THE OTHER THE OUTPUT DRIVE QUILL

42° GEARBOX

UH-1H TAIL #16197

TEST CONDUCTED 27 NOV 1973 AT SCOTT AFB




ONE CURVE REPRESENTS INPUT DRIVE QUILL, THE OTHER THE OUTPUT DRIVE QUILL.

42° GEARBOX

UH-1H TAIL #66-01087

INPUT DRIVE QUILL


TEST CONDUCTED 28 NOV 1973 AT SCOTT AFB



42° GEARBOX

UH-1H TAIL #15949


TEST CONDUCTED 28 NOV 1973 AT SCOTT AFB



ONE CURVE REPRESENTS INPUT DRIVE QUILL, THE OTHER OUTPUT DRIVE QUILL

42° GEARBOX UH-1M TAIL #59519

TEST CONDUCTED 30 NOV 1973 AT SCOTT AFB



UH-1M TAIL #15200

Figure 1 is a log-log plot showing the relationship between Rate (Y-axis) and Potentiometer Level (X-axis). The Y-axis ranges from 1 to 10,000, and the X-axis ranges from 1 to 10,000. Two curves are plotted: a solid line labeled 'OUTPUT QULL' and a dashed line labeled 'INPUT QULL'. Both curves show a sharp decrease in rate as the potentiometer level increases, with the output rate being lower than the input rate for levels above 10.


Potentiometer Level	Input Rate (Dashed Line)	Output Rate (Solid Line)
1	~600	~100
10	~400	~100
20	~300	~60
50	~100	~20
100	~30	~5
200	~10	~1

ABB6012 - GEARBOX SERIAL NUMBER

42° GEARBOX

UH-1H TAIL #69-15771

TEST CONDUCTED 6 DEC 1973 AT SCOTT AFB



ONE CURVE REPRESENTS INPUT QUILL, THE OTHER THE OUTPUT QUILL GEARBOX REMOVED FOR TEARDOWN ANALYSIS.

NOTE: SCALPED AREA DENOTES NEEDLE SWING.


ABB2667 - GEARBOX SERIAL NUMBER

42° GEARBOX

UH-1H TAIL #66-16879

TEST CONDUCTED 13 DEC 1973

AT BI-STATE AIRPORT



CURVE REPRESENTS THE OUTPUT DRIVE QUILL. GEARBOX REMOVED FOR TEARDOWN ANALYSIS.


NOTE: SCALPED AREA DENOTES NEEDLE SWING.

GEARBOX B13-3800

42° GEARBOX

UH-1M TAIL #66-15190

TEST CONDUCTED 12 DEC 1973 AT BI-STATE AIRPORT



ONE CURVE DEPICTS INPUT DRIVE QUILL, THE OTHER OUTPUT DRIVE QUILL.
GEARBOX REMOVED FOR TEARDOWN ANALYSIS.

NOTE: SCALPED AREA DENOTES NEEDLE SWING.

AB 1101 GEARBOX SERIAL NUMBER

281st Aviation Company Bi State Airport


6 Aug 74

90° Gear Box

42° Gear Box Input

42° Gear Box Output

A/C 60630 UH-1C
6600 RPM N₂




NOTE: 90° Gear Box _____
42° Gear Box Input _____
42° Gear Box Output _____



Duplex Ball Bearing
S/N 8199-H-2
Outer Race



Duplex Ball Bearing
S/N 8199-H-2
Cage



Roller Bearing
S/N 147403
Outer Race




Roller Bearing
S/N 147403
Rollers




Roller Bearing
S/N 21020
Inner Race



Roller Bearing
S/N 21020
Outer Race



Duplex Ball Bearing
S/N 8199-H-1
Cage



Roller Bearing
S/N 21020
Rollers



Duplex Ball Bearing
S/N 8112-H-1
Outer Race



Duplex Ball Bearing
S/N 8112-H-1
Inner Race



Duplex Ball Bearing
S/N 8112-H-1
Cage




Duplex Ball Bearing
S/N 8112-H-2
Outer Race

30 Jul 74


42° Gear Box Input { Portside
 42° Gear Box Output {
 90° Gear Box Case Half Mount Bolt

A/C 69-15550 UH1H
 . 6600 RPM N₂



NOTE: 42° Gear Box Input _____
 42° Gear Box Output _____
 90° Gear Box _____

SUMMARY CHART OF 10 90° GEAR BOX
ASSEMBLIES SHOWING DATA SCATTER




NOTE: Two assemblies showed high rates and levels when compared to the general scatter

1 Aug 74

90° Gear Box A 133069
 42° Gear Box Input B138813
 42° Gear Box Output

A/C 66-15200 UH-1H
 6600 RPM N₂




NOTE: 90° Gear Box _____
 42° Gear Box Input -----
 42° Gear Box Output - - - - -

1 Aug 74

42° Gear Box Input A131639
 90° Gear Box ABC 2892
 42° Gear Box Output

A/C 66-0529 UH-1M
 6600 RPM N₂




NOTE: 42° G/B Input _____
 90° G/B _____
 42° G/B Output _____

1 Aug 74

#3 Hanger Bearing A 2064529

#2 Hanger Bearing A 2052529


Mast Bearing

A/C 66-0529 UH-1M
6600 RPM N₂

281st Aviation Company Bi State Airport
 #3 Hanger Bearing A20-43493
 42° Gear Box Input B13-9384
 90° Gear Box B13-5077

5 Aug 1974

A/C 65-9884 UH-1D
 6600 RPM N₂




NOTE: #3 Hanger Bearing _____
 42° Gear Box Input - - - - -
 90° Gear Box - - - - -

6 Aug 74

#1 Hanger Bearing

Input Drive Quill

A/C UH-1C 60630
6600 RPM N₂


NOTE: #1 Hanger Bearing _____
Drive Quill -----

7 Aug 74

Mast Bearing

Input Drive

A/C 65-9771 UH-1H

6600 RPM N_2 


NOTE: Mast Bearing _____
Input Drive-----

6 Aug 74

#2 Hanger Bearing


#3 Hanger Bearing

Mast Bearing

A/C UH-1C 60630
6600 RPM N₂

#1 Hanger Bearing

Mast Bearing


A/C 66-15071 UH-1C
6600 RPM N₂

NOTE: #1 Hanger Bearing _____
Mast Bearing -----

6 Aug 74

90° Gear Box B13-3307
 42° Gear Box Output BBB-1894
 #2 Hanger Bearing A20-15990

A/C 66-15071 UH-1C
 6600 RPM N₂




NOTE: 90° G/B _____
 42° G/B output _____
 #2 Hanger Bearing _____

6 Aug 74

42° Gear Box Input . BBB-1894
#3 Hanger Bearing A20-31517
Input Drive Quill

A/C 66-15071 UH-1C
6600 RPM N₂



NOTE: 42° G/B _____


#3 Hanger Bearing -----

Input Drive Quill _____

8 Aug 74

90° Gear Box
#3 Hanger Bearing
#2 Hanger Bearing


A/C 65-9519 UH-1M
6600 RPM N₂



NOTE: 90° Gear Box B13-8655
#3 Hanger Bearing A20-26938
#2 Hanger Bearing A20-57910

Input Drive Quill

Mast Bearing


A/C UH-1M 65-9519
6600 RPM N₂

NOTE: Input Drive Quill _____
Mast Bearing -----

9 Aug 74

42° Gear Box Input
#1 Hanger Bearing

A/C UH-1M 66-15091
6600 RPM N₂



NOTE: Aircraft tested while raining
42° G/B input _____
#1 Hanger Bearing-----

AD-A040 130

PARKS COLL OF SAINT LOUIS UNIV CAHOKIA ILL F/G 1/3
APPLICATIONS OF THE SHOCK PULSE TECHNIQUE TO HELICOPTER DIAGNOS--ETC(U)
FEB 75 T C MAYER, E F COVILL, J A GEORGE DAAJ01-72-A-0027

UNCLASSIFIED


3 OF 3

AD
A040 130

100%


END

DATE
FILMED
6-77



90° Gear Box
 42° Gear Box Output
 42° Gear Box Input


A/C UH-1H 70-16354
 6600 RPM N₂



NOTE: 90° Gear Box _____
 42° Gear Box Output -----
 42° Gear Box Input - - - - -

Generator Drive Gear
Input Drive
Mast Bearing

A/C UH-1H 70-16354




NOTE: Generator Drive Gear _____
Input Drive _____
Mast Bearing _____

14 Aug 74

42° Gear Box Output

Mast Bearing

A/C UH-1D 66-16779
6600 RPM N₂


NOTE: 42° Gear Box Output _____

Mast Bearing-----

14 Aug 74

90° Gear Box
42° Gear Box Input


A/C UH-1D 66-16779
6600 RPM N_2



NOTE: 90° Gear Box _____
42° Gear Box -----

14 Aug 74


Input Drive Quill

A/C UH-1D 66-16779
6600 RPM N_2 

16 Aug 74

Mast Bearing

Input Drive Quill


A/C 66-01087 UH-1H
6600 RPM N₂

NOTE: Mast Bearing

Input Drive Quill-----


21 May 74

Input Drive Quill

A/C 63-8784
6600 RPM N₂

42° Gear Box Input
42° Gear Box Output
90° Gear Box


A/C 64-13740 UH-1H
6600 RPM N₂



NOTE: 42° Gear Box Input _____
42° Gear Box Output -----
90° Gear Box

18 Sep 74

OH-58-A
A/C# 72-21418
T/R 6180 RPM
Main Rotor 350 RPM
N₂ - 103%




AVSCOM FLIGHT DETACHMENT
St. Louis International Airport

18 Sep 74

Hanger Bearings

OH-58A
A/C# 72-21418
T/R 6180 RPM
Main Rotor 350 RPM
N₂ - 103%




AVSCOM FLIGHT DETACHMENT
ST. LOUIS INTERNATIONAL AIRPORT

18 Sep 74

90° Gear Box

OH-58A
A/C# 72-21418
T/R 6180 RPM
Main Rotor 350 RPM
N₂ - 103%




7.5 FIELD DATA (Ft. Rucker)

Ft. Rucker, Al. (U.S. Army Test Board)

13 Jun 74


#3 Hanger Bearing

A/C - BC 13
6600 RPM N₂




#4 Hanger Bearing A20-34779

A/C - BC 13
6600 RPM N₂




#3 Hanger Bearing

A/C - BC 14
6400 RPM N₂ full right
pedal



#3 Hanger Bearing

A/C - BC 14
Flight Idle




Ft. Rucker, Al. (U.S. Army Test Board)

13 Jun 74


#4 Hanger Bearing

A/C - BC 14
6400 RPM N₂ full left
pedal



#4 Hanger Bearing

A/C - BC 14
Flight Idle




Ft. Rucker, Al. (U.S. Army Test Board)

14 Jun 74

#3 Hanger Bearing

A/C - BC 13
6600 RPM N₂




Ft. Rucker, Al.


14 June 74

Hanger Bearing

A/C BC 13
6600 RPM N_2




"Inspected Damage Free Bearing Assembly" Typical of new or low
time assemblies tested.




Scatter Diagram
Transmission Input Drive Quill;
Ground Runs, $N_2 = 6600$ RPM.

--- Bearcat 13
Transmission S/N ABU-11067 (M-6)



Scatter Diagram
Transmission Mast Bearing Assembly

. Aft
 Δ Starboard
 ∇ Forward
 x Port (Normal Attachment)



Effect of Sensor Mounting
 On Mast Bearing Reading

Ft. Rucker, Al.


13 June 74

42° Gear Box

#B13-4312 (F-B)

A/C BC 13

6600 RPM N₂



Ft. Rucker, Al.


13 June 74

42° Gear Box

S/N B13-9881 (F-6)

A/C BC-14

6600 RPM N₂



Damage Implant Catagorized as C D


Duplex 143 BI 007

S/N 41100 - 1 & 2

Average Data Scatter of 3 runs


42° g/b

A/C - BC 14
6600 RPM N₂




42° g/b


A/C - BC14
6600 RPM N₂



42° Gearbox

A/C - BC 14
6600 RPM N₂





TIE-DOWN TESTS FORT RUCKER, AL.

BEARCAT 14 (S/N 65-9846)


run	symbol	engine rpm	rudder pedal
1	----	flight idle	neutral
2	•	6400	full right
3	Δ	6400	full left
4	x	6600	neutral
5	o	6600	full right
6	▽	6600	full left

Ft. Rucker, Al. (U.S. Army Test Board)

14 Jun 74

Input Drive Quill ABU-11067 (M-6)


A/C - BC 13
6600 RPM N_2



14 Jun 74

Mast Bearing

A/C - BC 13
6600 RPM N_2




7.6 DAMAGED GEARS

Mean Profiles- Damaged Gears

42° Gear Box


SN B13-1561



NOTE: Position 1 -----
 Position 2 _____
 Parks designed attachment _____

Mean Profiles - Damaged Bearing

42° Gear Box
SN B13-1561



NOTE: Position 1 -----
Position 2 -----
Parks designed attachment -----

BEST AVAILABLE COPY

7.7 SKF Report

FINAL REPORT
ON
THE APPLICATION OF THE SHOCK PULSE METER IN
DETECTING GEAR DAMAGE ON THE UH-1 42° GEAR BOX

FEBRUARY 1975

Reported: *SC Hyman*

Approved: *W. H. Lutz*

Released: *VE Taylor*

SKF Report: AL75Q002

SKF Code:

Contract No.: P.O. 9716

Submitted to:

Parks College of Aeronautical Technology
St. Louis University
Cahokia, Illinois 62206

Table of Contents

	Page
I. Test Object and Approach	158
II. Test Results	160
A. Gear Box S/N A13-830	160
B. Gear Box S/N B13-1561	163
C. Gear Box S/N BBB-1253	166
D. Summary of Results of Shock Pulse Testing	166
E. Results of Vibration Measurements on Operating Gear Boxes	167
III. Conclusions	168
IV. Recommendations	169
V. Enclosures	

I. Test Objective and Approach:

In the past, damage detection has consisted mainly of vibrational data analysis. A new diagnostic tool in the field of bearing damage detection that has been recently introduced is the SKF MEPA-10A Shock Pulse Meter. The principle of operation of this unit is that a damaged bearing in a machine generates mechanical shocks, which cause brief, high frequency vibrations to emanate from the point of impact. The pulse of energy is governed in its travel by the speed of sound in the structural material, not by the spring-mass characteristics of the mounting structure. It is attenuated at each mechanical interface and decays in amplitude in proportion to the distance and damping characteristics of the material through which it is travelling. A resonant accelerometer is used as the pulse sensor and its output is fed into an amplifier tuned to the accelerometer's resonant frequency. After signal processing, the output is displayed on a meter having a 20,000:1 dynamic range. The meter displays shock pulse, rate of occurrence and amplitude. It is then possible to plot a curve of these two parameters, which is a revealing measure of bearing condition.

Because of the successful results obtained in detecting rolling bearing damage, SKF Industries was contracted by Parks College of St. Louis University to establish the feasibility of, and determine a diagnostic approach for, the use of mechanical shock emissions to determine the condition of gears in an operating helicopter gear box. The tests were conducted on three UH-1 42° gear boxes. Each gear box was tested on an SKF test fixture which had been suitably modified for this series of tests. The fixture is shown in Enclosure 1. As shown, the drive motor is belt coupled to a pulley which was changed to vary the gear box speed. The input quill was coupled to

this pulley and was driven by it. The output quill was connected to a hydraulic pump which served to dissipate the energy transmitted, and whose pressure, and therefore load, could be varied with a manually operated valve.

The gear boxes were driven initially by a 15 horsepower induction motor and drove an IMO 3D hydraulic pump (with 156 rotor.)

Enclosure 2 shows a curve of oil viscosity as a function of temperature for the oil used in both pumps during testing. Enclosure 3 relates oil viscosity to horsepower as a function of the pump pressure for the IMO 3D pump, and Enclosure 4 does this for the IMO A6D pump.

Thus, by controlling pump pressure and monitoring oil temperature, the gear box applied load was determined. The gear boxes tested were operated at speeds of 3560 RPM and 1500 RPM. These speeds were held within 2%. At each speed two different loads, 2 horsepower and 4 horsepower at the lower speed and 2 horsepower and 10 horsepower at the higher speed, were applied. Early test results indicated that a greater load was desirable to more nearly approximate flight loads of 25 to 90 horsepower. Therefore an IMO A6D pump (with 137 rotor) and a 50 horsepower induction motor were installed on the fixture. This increased the drive and load capability of the test rig to 34 horsepower.

Shown in Enclosure 36 is a listing of the tests performed during the program in the order in which they were done. Test speeds, loads applied and gear implant conditions are also tabulated. This enclosure serves as a reference and guide for the following Test Results section.

II. Test Results

The first step in the program was to establish optimum sensor locations for detecting gear damage. After examination of the gear box drawing, four candidate positions were chosen. Data obtained from these points in initial testing was not sufficiently different to clearly indicate one location as superior. Consequently, in accordance with the theory of shock pulse operation, a location was selected which had the most direct mechanical path to the gear mesh. A spot located over the roller bearing on the input quill was selected. An aluminum block conforming to the shape of the housing was fabricated and after the paint was removed from that area of the gear box housing, the block was bonded to the housing. A second or backup spot was selected on the base opposite to the oil level gage. This location was selected because the gear box structure in this location was suitable for mounting an accelerometer and there was also a direct mechanical path to the gear mesh. Enclosure 5 shows the sensor locations.

The test results are presented for each of the three gear boxes tested and sequentially for each gear box tested.

A. Gear Box S/N A13-830

Gear Box S/N A13-830 was the first gear box tested. Enclosures 6 and 7 depict the base line data obtained for this gear box. At 1480 RPM, shock emission profiles were taken with 2.9 and 4.25 horsepower loads and at 3560 RPM with 2.6 and 10.4 horsepower loads. During Test 1, as can be seen from the data, the shock level increased mainly as a function of speed and not of load.

Test 3 was then conducted after damaged gears had been installed into this gearbox. The gear box was operated at 1480 RPM and 3580 RPM and loaded with 2.9 horsepower and 4.25 horsepower at the lower speed and 2.6 and 10.4 horsepower respectively at the higher speed.

Enclosure 8 shows a picture of these gears prior to their insertion into the gear box. The upper picture is that of the output gear, which has pieces of gear teeth missing. This was due to an earlier gear failure in another gear box. These gears had not, however, been previously run as a set in this gear box. Test 3 data with the damaged gears is shown in Enclosures 9 and 10. Position 2 data in Enclosure 9 at 1480 RPM shows higher shock levels with the damaged gears than with the undamaged ones, shown in Enclosure 6. At the higher speed, however, the shock level was slightly lower for damaged gears than for undamaged gears as is seen when comparing Enclosure 10 with Enclosure 7.

Since these damaged gears had not been operated as a set previously, the severity of shock generation by any given damage and the specific kinematics of the contact between the damaged surface is not known. In addition, the 2 to 10 horsepower load placed on the gear box was much less than the 25 to 90 horsepower load presented to the gear box in a helicopter. To provide a more representative load the previously discussed motor and pump change was made. Test 4 was then conducted at 3540 RPM and with the same damaged gears as in the previous tests, however, new higher loads were applied to the gear box. Tests at these new loads indicated approximately a 20% increase in the shock level for this gear box for both position 1 and position 2, as can be

seen by comparing Enclosure 11 to Enclosure 10 data. When comparing Enclosure 11 data with that for undamaged gears installed in the same gear box, at the same speed, however (Test 1 - Enclosure 7), no significant shock level trend is evident as a function of increased load.

A third set of gears was installed in this same gear box. These were also damaged gears. The severity of damage is shown in Enclosure 12. Test 5 was run at the test speeds of 1510 and 3540 RPM with the new applied loads of up to 34 horsepower. Data obtained is shown in Enclosures 13 and 14.

The curves taken for damaged gears in Enclosure 11 and the lower value curves in Enclosure 14 show only a slight variation when compared to Baseline undamaged gear data of Enclosure 7. Enclosure 13 data, at lower speed for damaged gears, when compared to Enclosure 6 data, at the same RPM for undamaged gears, also shows only a small change in shock level between damaged and undamaged gear sets at the 4 horsepower to 5 horsepower applied load level.

One event of significance that occurred early in test number 5 at 3540 RPM and at 13 HP load was a sharp increase in shock level for a period of about 2 minutes. The data obtained during this time period is shown in Enclosure 14 as the higher shock value curves. The rapid increase in shock level did not recur during further testing. A post-test examination of the oil in the gear box showed fine metal particles throughout the oil. The probable cause of the increase in shock level is, therefore, believed to be the passage of the particulate matter through the bearing load zone since bearing rolling element encounter with particulate matter is known to generate shock pulses.

B. Gear Box S/N B13-1561

The second gear box for which base line information was taken was S/N B13-1561. This baseline test is designated as Test 2 and the results are shown in Enclosures 15 and 16. This baseline data was obtained while the test rig was in the low horsepower configuration. The test was conducted at the same speeds and applied loads as the baseline test of gear box S/N A13-830. The data is similar to the baseline data obtained from gearbox S/N A13-830 during Test 1 (Enclosures 6 and 7). The largest shock level difference observed was that the position 2 shock level at 3580 RPM, Enclosure 16, was about one half that of S/N A13-830 gear box baseline value shown in Enclosure 7.

This second gear box, SN B13-1561, was also retested with the higher 13 to 33 HP loads (Test No. 2). Enclosure 17 shows the Baseline data obtained at 3540 RPM. There was again no distinct trend of shock level to follow load. Slight changes in shock level data compared to that in Enclosure 16 were observed in an increase in position 1 data and a decrease in position 2 readings. Because the data showed no marked change with these higher loads at 3540 RPM, the lower speed runs were not repeated.

This gear box was then removed from the fixture and the gears removed. They are shown in Enclosure 18. An artificial damage was inflicted on the output quill gear with a hand grinder. The damage was approximately 1/4" long, 1/16 inch wide and was placed in the contact area of one gear tooth.

After the gear box was remounted in the fixture, Test 6 was conducted. Data taken at 1520 RPM, and 5 and 14.5 horsepower loads is presented in Enclosure 19. Position 1 data indicates a high rate of shocks at low shock levels which is traditionally indicative of solid particulate matter in the lubricant.

Position 2 data was slightly lower in shock level than experienced in previous baseline runs for this speed.

A second part of Test 6 was conducted to assure the reliability of data obtained from position 2 (verify that the bonding of the accelerometer block did not adversely affect the data), a hole was drilled and tapped in the Gear Box housing at the Position 2 location, to mount the accelerometer block directly to the gear box, thereby eliminating any potential interface effect of the glue. Data was obtained with the block bonded on. The test was conducted at 3540 RPM and 13.25 horsepower loads. The hole was then drilled and tapped, the accelerometer stud mounted and the test repeated. The data obtained with the block bonded on and the repeat data are shown for comparison in Enclosure 20. There was a slight increase in both rate and level with the stud mounted accelerometer. The difference, however, lies within the normal 10% to 20% variation of readings from run to run.

Test 6 was continued with the accelerometer stud mounted. Enclosure 21 presents the shock emission data obtained for the artificially damaged gear implant at a speed of 3540 RPM and 13.25 and 33.75 horsepower loads.

This gear box was operated for an extended period of time and data taken at position 2 periodically to monitor the trend or growth in shock level with time. Enclosure 22 shows data acquired

after running for 5, 10, 30 and 50 minutes respectively. There was a 4 to 1 growth in shock level which normally indicates damage growth. The gear box was run for an additional hour on the following day. The curve shape and shock level did not change from that shown for 50 minutes in Enclosure 22. Visual examination of the gear box oil revealed a large amount of fine metal particles. The most likely source of these is the gear which had been artificially damaged. Because of the roughness at the edges of the artificially damaged area of the gear metal burrs could break off quite easily. Gear wear and spalling occurring naturally will also exhibit the tendency to produce a particulate debris which would have a similar effect on shock emission, introducing the possibility that the shock pulse technique may monitor gear wear or damage growth by monitoring the shock pulse affect of particulate matter in the oil or observed shock emission levels.

Test 7 was conducted using an input quill assembly with artificial damage on the gear implanted in this same gear box. The damage had been inflicted on the gear with a carbide scribe. Burring that occurred during the scribing was not removed. A photo of this gear is shown in Enclosure 23. The output quill in which the gear had been previously artificially damaged by the hand grinder remained in the gear box. Initial readings showed a shock level of about 9 at position 2. This quickly changed to about 25 within a minute or two after the Test was started and took the shape of the curve shown in Enclosure 24. Enclosure 25 shows data obtained at position 1 while Enclosure 26 shows data obtained using a Parks College type VD-3 accelerometer holder mounted to a bolt on the input quill housing. There was some variation in shock rate with time as can be seen in the three enclosures. This type of variation had not been

observed in the past. Also, there were occasional but regular spikes observed which gave readings of up to 2000 pulses per second. Increases in the rate of small shocks is characteristic of particulate contaminant in the lubricant passing through the bearings.

Upon request by Parks College, a 7th Test was performed with an "unknown condition" input quill assembly supplied by Parks College. It was implanted in the gear box and data again taken. This time the rate readings were also variant. The data is shown in Enclosures 27, 28 and 29. The readings obtained also showed extremely high shock levels indicative of bearing damage. This implant rather than having a gear damage had a bearing implanted with damaged balls, a picture of which is shown in Enclosure 30. The ability of the MEPA-10A to isolate bearing damage in an operating gearbox was again demonstrated.

C. Gear Box S/N BBB-1253

A third gear box was tested at the standard test speeds and loads. Baseline data was obtained to establish consistency of baseline level from gear box to gear box. The data is shown in Enclosure 31 and 32.

D. Summary of Results of Shock Pulse Testing

The baseline shock level determined on the three gear boxes at 1490 RPM varied from 25 to 35 in value while at 3580 RPM the variation was between 50 and 200.

Baseline shock level and its variation from gear box to gear box are so low compared to bearing damage levels that they do not markedly affect the ability of the shock pulse technique to detect bearing implant exhibited shock levels of ten times the baseline values, thus variations of 30% or even four to one in baseline level

do not affect the capability of the shock pulse meter to detect bearing damage.

The results of this test program, however, indicate that the same consistent correlation does not exist for the gear-damaged implants tested.

The tenfold increase in shock level experienced during Test 5, a test of damaged gear implanted in gear box S/N A13-830, and the growth in shock level from 65 to 160 in Test 6, a test of an artificially damaged gear in gear box S/N B13-1561 serve as evidence of the capability of the shock pulse technique to detect the growth of damage or wear in a gear set by measuring the effect of wear debris on emitted shock pulse level.

A correlation of a specific gear damage severity to a specific shock level emitted is not evidenced in the test data.

Gear mesh shocks (those occurring at gear mesh frequency) were not sensed as evidenced by the fact that they occur at 3 to 5 times the maximum shock rates observed during testing. This indicates they were not of sufficient magnitude to be sensed by the standard MEPA-10A Shock Pulse Meter.

Gear damage sourced shocks are similarly not evidenced in the data taken again, presumably because they are too small in amplitude to be sensed by the standard MEPA-10A Shock Pulse Meter.

E. Results of Vibration Measurements on Operating Gear Boxes

In addition to the testing with the MEPA-10A, single axis vibration measurements were also made. This was done using an SKF Industries MEB-17A Vibration Amplifier, which determines vibrational velocity from an accelerometer input signal. This unit has three frequency bands (50 to 300 HZ, 300 to 1800 HZ and 1800 to

10,000 HZ) and is used for production vibration testing of bearings at SKF. The sensor used was the accelerometer located at position 2. The data obtained is shown in Enclosure 33. It is evident that vibration velocity levels are not a conclusive measure of gear damage. Although there appears to be some correlation between damaged and vibration readings, this is true only for certain damaged gears and not for all. At the same time, a tape recording of the vibrational velocity signal output was made. This data was later analyzed on a B&K 1/3 Octave Frequency Spectrum Analyzer.

The B&K traces are shown in Enclosures 34 and 35. As can be seen from the data, the gear mesh frequency predominates, but damaged gears do not show marked differences (increase in amplitude) as compared to undamaged gears, confirming the statement that vibration measurements are an inconclusive measure of gear damage.

CONCLUSIONS:

Three UH-1 helicopter 42 degree gear boxes with several different types of gear damage have been subjected to shock pulse monitoring during runs at two different loads and at two speeds. From the data obtained during testing, the following has been determined:

1. The MEPA-10A as used can supply warnings as to the onset of damage in a gear box. If damage originates in the bearings, an indication directly correlated with damage is received. If the damage originates in gears, the indication is due to the sensing of particulate contaminant passing through the bearings.

2. The MEPA-10A appears capable of detecting a secondary effect of gear damage in an operating 42° UH-1 helicopter gear box since, in this gearbox, the lubricant is captive in the gearbox. Metal chips and particles are the products of the mesh of damaged gear teeth and tend to pass through the bearings as the oil in the gear box circulates. Shock level and rate increases accompany their passage.
3. The shock pulse technique has again proven successful in isolating a damaged bearing in a gear box. Standard shock pulse analysis techniques (shock emission profile) using the MEPA-10A were not found in the present study to provide a direct indication of the degree of gear damage.
4. Vibrational velocity measurement, analyzing the signal either in three, two and one-half octave bands, or one-third octave analysis of the audio-frequency spectrum has failed to provide any consistent indication of damage.

RECOMMENDATIONS

The following further work is recommended:

1. To establish fully whether shock pulse indications due to debris entering the lubricant correlate with the gear damage condition from inception through advanced stages:
 - (a) Modify the existing test fixture to permit higher gear box loading. Conduct gear endurance tests to obtain naturally caused damage and allow damage to grow. This will allow realistic observation of damage progression by shock pulse monitoring.

- (b) Measure the effect of the gear emitted debris on shock emission profiles and correlate through periodic gear box examination to level of gear damage including wear. Also, correlate with analysis results of debris content in the oil.
- 2. As a more advanced approach to the establishment of a gear damage detection capability, work is recommended toward the development of more sophisticated shock pulse analysis techniques capable of examining the gear damage emitted shocks in time intervals between the main gear mesh shocks.


It is apparent from the B&K traces that the amplitude of vibration emitted at the gear mesh frequency is very high, due to the meshing impact. The damaged areas come in contact only as the teeth slide across one another. It appears that the impact of the damage as compared to the impact of the teeth mesh is quite small. The shock pulses emitted by the damage also would occur at a higher frequency. Since the MEPA-10A has proven so successful in the measurement of bearing damage, modification of the electronics should be considered to investigate the shock pulses emitted in time segments between the meshing of teeth, as a measure of gear damage severity.

A diagnostic approach that would permit this and also provide automated analysis of the shock emission data can be implemented by the following method.

The data taken during testing indicates shock rates on the order of several hundred per second, using the present lower threshold limit of "1" on the MEPA-10A. The gear mesh should have caused shock rates 3 to 7 times higher than these values. The shock rate due to damage, therefore, must have occurred at levels less than "1.0." To measure these small shocks it is necessary first, to increase the sensitivity of the MEPA-10A input circuitry, thereby allowing levels of less than 1.0 to be measured.

Next, by using signals with a level greater than one as an "inhibit" on the Pulse Integrator circuitry, the MEPA can be made to look only at shock levels less than one. The length of time of the inhibit would have to be determined empirically. This approach will permit analysis of smaller shocks occurring in the time segment between the larger shocks. It would then only be necessary to add level discrimination and logic circuitry to the design to enable automatic data analysis.

Enclosure 1



74 548


GEAR BOX
TEST FIXTURE

F-4186A R100

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

A.S.T.M. STANDARD VISCOSITY-TEMPERATURE CHARTS
FOR LIQUID PETROLEUM PRODUCTS (D 341)
CHART B: SAYBOLT UNIVERSAL VISCOSITY, ABRIDGED

D T E HYDRAULIC OIL
Used in IMO 3D
AND IMO A6D PUMPS



VISCOSITY, SAYBOLT UNIVERSAL SECONDS

VISCOSITY, SAYBOLT UNIVERSAL SECONDS




IMO 3D PUMP (WITH 156 ROTOR)

ENCLOSURE 3

10 X 10 TO THE INCH 359 S
KEUPPEL & ESSER CO. WILSON, N.J.

HEAD
FEET


18
16
14
12
10
8
6
4
2
0



WR
6/17/74 174
10/11/74


IMO A6D PUMP (WITH 137 ROTOR)

ENCLOSURE 4



WR
8/22/74 172

ENCLOSURE 5



74 548

42° Gear Box

F-4135-A R103


RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

S/N A13 - 830

BASELINE DATA

SPEED: 1480 RPM
AMBIENT: 82° F
GEAR BOX TEMP: 103° F

ENCLOSURE 6



SKF A1 169 Art. 1048-4 Repro 169S9 7500 7103

S/N A13 - 830


BASELINE DATA

SPEED: 3560 RPM

AMBIENT: 35°F


GEAR BOX TEMP: 138°F at 2.6HP
150°F at 10.4HP

ENCLOSURE 7




SKF K 154 Art. 1048-4 Repro 16959 7500 7103

ENCLOSURE 8



OUTPUT GEAR - Test 3



INPUT GEAR - TEST 3

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

S/N A13 - 830


HEAVILY DAMAGED GEARS

SPEED: 1480 RPM

AMBIENT: 72°F

GEAR BOX TEMP: 100°F

ENCLOSURE 9



S/N A13 - 830
HEAVILY DAMAGED GEARS


SPEED: 3580 RPM

AMBIENT: 76°F

GEAR BOX TEMP: 140°F at 10.4 HP

128°F at 2.6 HP

ENCLOSURE 10



SKF KI 169 Art. 1048-4 Repro 16959 7500 7103

S/N A 13 - 830

HEAVILY DAMAGED GEARS


SPEED: 3540 RPM

AMBIENT: 86° F


GEAR BOX TEMP: 165°F at 33.75 HP

157°F at 13.25 HP


ENCLOSURE 11



SKF K1 169 Art. 1048-4 Repro 16959 7500 7103



OUTPUT GEAR - Test 5



INPUT GEAR - TEST 5

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.


F-4136A R109

S/N A 13 - 830

DAMAGED GEARS (2nd set)

SPEED: 1510 RPM
AMBIENT: 72°F
GEAR BOX TEMP: 103°F at 14.25 HP
99°F at 5 HP

ENCLOSURE 13



SKF K1 169 Art. 1048-4 Repro 1063 / 509 71 03

S/N A13 - 830

DAMAGED GEARS (2nd SET)


SPEED: 3540 RPM

AMBIENT: 82°F

GEAR BOX TEMP: 162°F at 33.75HP

153°F at 13.25HP

ENCLOSURE 14



S/N B 13 - 1561

BASELINE DATA


SPEED: 1490 RPM

AMBIENT: 85°F

GEAR BOX TEMP: 108°F at 4.25 HP

107°F at 2.9 HP

ENCLOSURE 15



SKE K1 169 Art. 1048-4 Repro 16959 756.0 1103

S/N B13 - 1561

BASELINE DATA


SPEED: 3580 RPM

AMBIENT: 75°F

GEAR BOX TEMP: 143°F at 10.4 HP

128°F at 2.6 HP

ENCLOSURE 16



SAFRI 169 Art. 1048-4 Repro 16959-5007103

S/N B13 - 1561

BASELINE DATA


SPEED: 3540 RPM

AMBIENT: 86°F

GEAR BOX TEMP: 186°F at 33.75 HP


180°F at 13.25 HP

ENCLOSURE 17




SNF KI 169 Art. 1048-4 Repro 16459 7500 7103

ENCLOSURE 18



INPUT GEAR - TEST 2



OUTPUT GEAR - TEST 2

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

F 4185A R100

S/N B13 - 1561

ARTIFICIALLY DAMAGED GEARS


SPEED: 1520 RPM

AMBIENT: 73° F

GEAR BOX TEMP: 107°F at 14.5 HP

105°F at 5 HP

ENCLOSURE 19



SRE K1 169 Art. 1048-4 Repro 16959 7500 7103

S/N B13 - 1561


ARTIFICIALLY DAMAGED GEARS

SPEED: 3540 RPM

AMBIENT: 78°F

GEAR BOX TEMP: 108°F at 13.25HP

ENCLOSURE 20



SKE KI 169 Art. 1048-4 Repro 16959 7500 7103

S/N B13 - 1561


ARTIFICIALLY DAMAGED GEARS

SPEED: 3540 RPM

AMBIENT: 78°F

GEAR BOX TEMP: 160°F at 33.75 HP
153°F at 13.25HP

ENCLOSURE 21




SKF K1 169 Art. 1048-4 Repro 16959 7500 7103

S/N B13 - 1561

ARTIFICIALLY DAMAGED GEARS

SPEED: 3540 RPM

ENCLOSURE 22



SEP 74



INPUT GEAR WITH SCRIBE MARKS - TEST 7


Enclosure 23

F-4136A R100

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

S/N B13 - 1561
DAMAGED GEAR
SPEED: 1490 RPM
AMBIENT: 66°F
GEAR BOX TEMP: 102°F
POSITION 2


ENCLOSURE 24



SKF K1 169 Art. 1048-4 Repro 16950 7500 7103

S/N B13 - 1561
DAMAGED GEARS
SPEED: 1490 RPM
AMBIENT: 68°F
GEAR BOX TEMP: 103°F
POSITION 1

ENCLOSURE 25



SKF 169 Ar. 1048-4 Repro 16959 75007103

S/N B13 - 1561

DAMAGED GEARS


SPEED: 1490 RPM

AMBIENT: 68°F

GEAR BOX TEMP: 104°F


POSITION 3

ENCLOSURE 26



S/N B13 - 1561
 DAMAGED BEARING
 SPEED: 1490 RPM
 AMBIENT: 70°F
 GEAR BOX TEMP: 82°F
 POSITION 2

ENCLOSURE 27




SKF KI 169 Art. 1048-4 Repro 169S9 75007103

S/N B13 - 1561
DAMAGED BEARING
SPEED: 1490 RPM
AMBIENT: 71°F
GEAR BOX TEMP: 90°F


POSITION 1

ENCLOSURE 28




S&K K1 169 Art. 1048-4 Repro 16959 7500 7103

S/N B13 - 1561
 DAMAGED BEARING
 SPEED: 1490 RPM
 AMBIENT: 71°F
 GEAR BOX TEMP: 95°F
 POSITION 3
 ENCLOSURE 29



ENCLOSURE 30



TEST 8 - BALL DAMAGE

F-4136A R100

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

S/N BBB - 1253


BASELINE DATA

SPEED: 1520 RPM

AMBIENT: 70°F


GEAR BOX TEMP: 98°F at 5 HP
103°F at 14.5HP

ENCLOSURE 31



S/N BBB - 1253
BASELINE DATA
SPEED: 3540 RPM
AMBIENT: 92°F
GEAR BOX TEMP: 173°F at 13.25HP
180°F at 33.75HP

ENCLOSURE 32



GEAR BOX	CONDITION	LOAD (HP)	SPEED (RPM)	LOW BAND 50-300 cps (μ in/sec)	MID BAND 300-1800 cps (μ in/sec)	HIGH BAND 1800-10000 cps (μ in/sec)
S/N A13-830	DAMAGED GEARS	33.75	3580	34k TO 64k	183k	123k
S/N B13-1561	UNDAMAGED	33.75	3540	64k TO 102k	274k	150k
S/N BBB-1253	UNDAMAGED	33.75	3540	60k TO 144k	348k	256k
S/N B13-1561	ARTIFICIAL DAMAGE	33.75	3540	238k	293k	220k
S/N A13-830	DAMAGED GEARS (2nd Set)	33.75	3540	219k	549k	402k
S/N BBB-1253	UNDAMAGED	14.5	1520	40k TO 56k	121k	44k
S/N B13-1561	ARTIFICIAL DAMAGE	14.5	1520	48k	311k	33k
S/N A13-830	DAMAGED GEARS	14.25	1510	220k	220k	37k


ENCLOSURE 33

P & K Vibrational Data

S/N A13-830
SPEED - 1520 RPM
LOAD - 9.75 HP
DAMAGED

40 DB = 1.16 in/sec


5
12/4
9/30/74
RMS
-40 DB
20 CPS
50 DB



S/N B88-1253
SPEED - 3540 RPM
LOAD - 38.75 HP
NO DAMAGE

60 DB = 1.16 in/sec

2
8/30/74
RMS
-50 DB
20 CPS
50 DB



ENCLOSURE 34

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.


B & K Vibrational Data

S/N B13-1561
SPEED - 1520 RPM
LOAD - 1.75 HP

ARTIFICIAL
DAMAGE

50 DB = 1.16 μ

3
9/11/74
RMS
-50 DB
20 CPS
50 DB




S/N B13-1561
SPEED - 3580 RPM
LOAD - 33.75 HP

NO DAMAGE

50 DB = 1.16 μ

1
8/28/74
RMS
-50 DB
20 CPS
50 DB




S/N B13-1561
SPEED - 3540 RPM
LOAD - 33.75 HP

ARTIFICIAL
DAMAGE

50 DB = 1.16 μ

4
9/13/74
RMS
-50 DB
20 CPS
50 DB



ENCLOSURE 35

RESEARCH LABORATORY **SKF** INDUSTRIES, INC.

TEST	ENCLOSURES	GEARBOX	GEAR CONDITION	SPEED (RPM)	LOADS (HP)	
					1	2
1	6	A13-830	Baseline	1480	2.9	4.25
	7	A13-830	Baseline	3560	2.6	10.4
2	15	B13-1561	Baseline	1490	2.9	4.25
	16	B13-1561	Baseline	3580	2.6	10.4
	17	B13-1561	Baseline	3580	13.25	33.75
3	9	A13-830	Heavily Damaged	1480	2.9	4.25
	10	A13-830	Heavily Damaged	3580	2.6	10.4
4	11	A13-830	Heavily Damaged	3540	13.25	33.75
5	13	A13-830	Damaged (2nd Set)	1510	5	14.25
	14	A13-830	Damaged (2nd Set)	3540	13.25	33.75
6	19	B13-1561	Artificial Damage	1520	5	14.5
	20	B13-1561	Artificial Damage	3540	13.25	
	21	B13-1561	Artificial Damage	3540	13.25	33.75
	22	B13-1561	Artificial Damage	3540	31.5	to 34.5 HP
(load varied with temp.)						
7	24	B13-1561	Damaged Gear	1490	14.25	Pos. 2
	25	B13-1561	Damaged Gear	1490	14.25	Pos. 1
	26	B13-1561	Damaged Gear	1490	14.25	Pos. 3
8	27	B13-1561	Damaged Bearing	1490	14.25	Pos. 2
	28	B13-1561	Damaged Bearing	1490	14.25	Pos. 1
	29	B13-1561	Damaged Bearing	1490	14.25	Pos. 3
9	31	BBB-1253	Baseline	1520	5	14.5
	32	BBB-1253	Baseline	3540	13.25	33.75

Enclosure 36

7.8 STATISTICAL SUMMARY OF SHOCK PULSE DATA

ITEM		\bar{x}	SD	SE
Hanger Bearings	Rate	185.19	85.76	11.67
Total	Level	502.4	943.14	128.35
42° G/B	Rate	149.05	121.71	18.78
	Level	106.5	79.59	12.28
90° G/B	Rate	114.375	31.1	10.99
	Level	75.0	54.71	19.34
Mast Bearing	Rate	87.27	38.82	11.7
	Level	72.73	29.61	8.93
Input Drive Quill	Rate	161.81	37.37	11.27
	Level	190.91	67.89	20.47
Hanger Bearings	Rate	273.64	52.06	15.7
Removed	Level	1836.36	1575.61	475.06
Hanger Bearings	Rate	172.0	78.59	12.43
Not Removed	Level	147.93	189.46	29.96
OH-58 Hangers	Rate	95	50.79	20.736
	Level	77	37.79	15.427
Hanger Bearings	Rate	170.23	84.35	12.86
Not Removed	Level	159	213.45	32.55
Hanger Bearings	Rate	271.67	72.37	20.89
Removed	Level	2254.17	2126.83	613.96
42° G/B	Rate	111.32	73.11	12.54
Not Removed	Level	102.147	124.24	21.31
42° G/B	Rate	337.22	195.02	65.01
Removed	Level	180.0	85.99	28.66
90° G/B	Rate	159.4	167.71	55.9
Not Removed	Level	68.3	54.94	18.31
Input Drive Quill	Rate	161.81	37.37	11.27
High & Low Rate and corresponding levels removed	Level	189.1	70.21	21.17
90° G/B Total	Rate	160.625	179.253	63.38
High & Low Levels removed and corresponding Rates	Level	750	54.71	19.34